

تمت مشاركة هذه المعلومة بإشارة مشاركة \*\*\*أبيض\*\*\* حيث يسمح بتبادلها Please note that this notification/advisory has been tagged as TLP \*\*\*WHITE\*\*\* where information can be shared or published on any public forums.

أو نشرها من خلال القنوات العامة.

national interests, NCA provides the weekly summary of published السيبراني الوطني، تود الهيئة مشاركتكم النشرة الأسبوعية للتُغرات المسجلة vulnerabilities by the National Institute of Standards and Technology the National Institute of Standards and Technology (NIST) من قبل (NIST) National Vulnerability Database (NVD) for the week from 28<sup>th</sup> التُسبوع من ۲۸ یولیو إلی ۳ National Vulnerability Database (NVD) of July to 3<sup>rd</sup> of August. Vulnerabilities are scored using the Common Common اغسطس. علماً أنه يتم تصنيف هذه الثغرات باستخدام معيار Vulnerability Scoring System (CVSS) standard as per the following حيث يتم تصنيف الثغرات بناء على Vulnerability Scoring System (CVSS) severity:

Critical: CVSS base score of 9.0-10.0 High: CVSS base score of 7.0-8.9 Medium: CVSS base score 4.0-6.9 Low: CVSS base score 0.0-3.9

في ضوء دور الهيئة الوطنية للأمن السيبراني للمساعدة في حماية الفضاء As part of NCA duties to help securing the cyberspace and protecting التالي:

عالى جدًا: النتيجة الأساسية لـ10.0-CVSS 9.0

عالى: النتيجة الأساسية لـ8.9-7.0 CVSS

متوسط: النتيجة الأساسية لـ6.9-CVSS 4.0

منخفض: النتيجة الأساسية لـ CVSS 0.0-3.9

CVE ID & Source	Vendor - Product	Description	Publish Date	Score	Severity
		A use-after-free issue was addressed with improved memory			
	I	management. This issue is fixed in iOS 16.7.9 and iPadOS 16.7.9,			
	I	Safari 17.6, iOS 17.6 and iPadOS 17.6, watchOS 10.6, tvOS 17.6,			
	I .	visionOS 1.3, macOS Sonoma 14.6. Processing maliciously crafted			_
CVE-2024-40782	Apple	web content may lead to an unexpected process crash.	2024-07-29	9.8	Critical
	I	In the Linux kernel, the following vulnerability has been resolved:			
		tcp_metrics: validate source addr length			
	I				
	I	I don't see anything checking that			
	I	TCP_METRICS_ATTR_SADDR_IPV4			
	I	is at least 4 bytes long, and the policy doesn't have an entry			
	I	for this attribute at all (neither does it for IPv6 but v6 is			
CVE-2024-42154	Linux	manually validated).	2024-07-30	9.8	Critical
	I	Weak authentication in Microsoft Dynamics 365 allows an			
CVE-2024-38182	Microsoft	unauthenticated attacker to elevate privileges over a network.	2024-07-31	9	Critical
	I	Uninitialized Use in Dawn in Google Chrome on Android prior to			
	I	127.0.6533.88 allowed a remote attacker to potentially perform			
	_	out of bounds memory access via a crafted HTML page.			
CVE-2024-6990	Google	(Chromium security severity: Critical)	2024-08-01	8.8	High
	I	Insufficient data validation in Dawn in Google Chrome on Android			
	I	prior to 127.0.6533.88 allowed a remote attacker to execute			
	_	arbitrary code via a crafted HTML page. (Chromium security			
CVE-2024-7256	Google	severity: High)	2024-08-01	8.8	High
	I	A vulnerability has been identified in Omnivise T3000 Application			
	I	Server (All versions). The affected system exposes the port of an			
	I	internal application on the public network interface allowing an			
CVE 2024 20070	C:	attacker to circumvent authentication and directly access the	2024.00.02	0.7	110-4
CVE-2024-38879	Siemens	exposed application.	2024-08-02	8.7	High
	I	A permissions issue was addressed with additional restrictions.			
CVE 2022 42019	Annla	This issue is fixed in macOS Sonoma 14. A sandboxed process may be able to circumvent sandbox restrictions.	2024-07-29	8.6	∐iah
CVE-2023-42918	Apple		2024-07-29	0.0	High
	I	A vulnerability has been identified in Omnivise T3000 Application Server (All versions >= R9.2), Omnivise T3000 Domain Controller			
	I	(All versions >= R9.2), Omnivise T3000 Domain Controller			
	I	(PDM) (All versions >= R9.2), Omnivise T3000 Froduct Data Management (PDM) (All versions >= R9.2), Omnivise T3000 Terminal Server (All			
	I	versions >= R9.2), Omnivise T3000 Terminal Server (All versions >=			
	I	R9.2), Omnivise T3000 Whitelisting Server (All versions >= R9.2).			
	I	The affected application regularly executes user modifiable code			
	I	as a privileged user. This could allow a local authenticated attacker			
CVE-2024-38876	Siemens	to execute arbitrary code with elevated privileges.	2024-08-02	8.5	High
<u> </u>		An unspecified SQL Injection vulnerability in Core server of Ivanti	202 : 00 02	3.3	
	I	EPM 2024 flat allows an authenticated attacker within the same			
CVE-2024-37381	Ivanti	network to execute arbitrary code.	2024-07-29	8.4	High
		The issue was addressed with improved checks. This issue is fixed			
	I	in macOS Sonoma 14.6, macOS Monterey 12.7.6, macOS Ventura			
CVE-2024-40781	Apple	13.6.8. A local attacker may be able to elevate their privileges.	2024-07-29	8.4	High

		An input validation issue was addressed with improved input			
		validation. This issue is fixed in macOS Sonoma 14.6, macOS			
CVE 2024 40000	Ammla	Monterey 12.7.6, macOS Ventura 13.6.8. An app may be able to	2024 07 20	0.4	11: ala
CVE-2024-40800	Apple	modify protected parts of the file system.  The issue was addressed with improved checks. This issue is fixed	2024-07-29	8.4	High
		in macOS Sonoma 14.6. An app may be able to modify protected			
CVE-2024-40811	Apple	parts of the file system.	2024-07-29	8.4	High
		An access issue was addressed with additional sandbox			
		restrictions. This issue is fixed in macOS Sonoma 14.6, macOS			
CVE-2024-40821	Apple	Monterey 12.7.6, macOS Ventura 13.6.8. Third party app extensions may not receive the correct sandbox restrictions.	2024-07-29	8.4	High
CVL-2024-40821	Арріе	The issue was addressed with improved checks. This issue is fixed	2024-07-29	0.4	riigii
		in macOS Sonoma 14.6, macOS Monterey 12.7.6, macOS Ventura			
CVE-2024-40828	Apple	13.6.8. A malicious app may be able to gain root privileges.	2024-07-29	8.4	High
		Zohocorp ManageEngine OpManager, OpManager Plus,			
CVE-2024-6748	ManageEngine	OpManager MSP and RMM versions 128317 and below are vulnerable to authenticated SQL injection in the URL monitoring.	2024-07-29	8.3	High
CVE-2024-0748	ivianageEngine	A vulnerability has been identified in Omnivise T3000 Application	2024-07-29	0.3	півіі
		Server (All versions), Omnivise T3000 Domain Controller (All			
		versions), Omnivise T3000 Network Intrusion Detection System			
		(NIDS) (All versions), Omnivise T3000 Product Data Management			
		(PDM) (All versions), Omnivise T3000 Security Server (All versions),			
		Omnivise T3000 Terminal Server (All versions), Omnivise T3000 This Client (All versions), Omnivise T3000 Whitelisting Server (All			
		Thin Client (All versions), Omnivise T3000 Whitelisting Server (All versions). The affected devices stores initial system credentials			
		without sufficient protection. An attacker with remote shell			
		access or physical access could retrieve the credentials leading to			
		confidentiality loss allowing the attacker to laterally move within			
CVE-2024-38877	Siemens	the affected network.	2024-08-02	8.3	High
		In the Linux kernel, the following vulnerability has been resolved:			
		ata: libata-core: Fix double free on error			
		did. Hadia core. Tix double free off effor			
		If e.g. the ata_port_alloc() call in ata_host_alloc() fails, we will			
		jump			
		to the err_out label, which will call devres_release_group().			
		devres_release_group() will trigger a call to ata_host_release(). ata_host_release() calls kfree(host), so executing the kfree(host) in			
		ata_host_alloc() will lead to a double free:			
		dta_nost_anoc() wiii lead to a dodole nee.			
		kernel BUG at mm/slub.c:553!			
		Oops: invalid opcode: 0000 [#1] PREEMPT SMP NOPTI			
		CPU: 11 PID: 599 Comm: (udev-worker) Not tainted 6.10.0-rc5 #47			
		Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014			
		RIP: 0010:kfree+0x2cf/0x2f0			
		Code: 5d 41 5e 41 5f 5d e9 80 d6 ff ff 4d 89 f1 41 b8 01 00 00 00			
		48 89 d9 48 89 da			
		RSP: 0018:ffffc90000f377f0 EFLAGS: 00010246			
		RAX: ffff888112b1f2c0 RBX: ffff888112b1f2c0 RCX:			
		ffff888112b1f320 RDX: 00000000000400b RSI: fffffffc02c9de5 RDI:			
		ffff888112b1f2c0			
		RBP: ffffc90000f37830 R08: 000000000000000 R09:			
		00000000000000			
		R10: ffffc90000f37610 R11: 617461203a736b6e R12:			
		ffffea00044ac780 R13: ffff888100046400 R14: fffffffc02c9de5 R15:			
		00000000000006			
		FS: 00007f2f1cabe980(0000) GS:ffff88813b380000(0000)			
		knlGS:000000000000000			
		CS: 0010 DS: 0000 ES: 0000 CR0: 0000000080050033			
		CR2: 00007f2f1c3acf75 CR3: 0000000111724000 CR4:			
		000000000750ef0 PKRU: 55555554			
		Call Trace:			
		<task></task>			
		?die_body.cold+0x19/0x27			
		? die+0x2e/0x50			
		? do_trap+0xca/0x110			
		? do_error_trap+0x6a/0x90 ? kfree+0x2cf/0x2f0			
		? ktree+0x2ct/0x2t0 ? exc_invalid_op+0x50/0x70			
		? kfree+0x2cf/0x2f0			
		? asm_exc_invalid_op+0x1a/0x20			
		? ata_host_alloc+0xf5/0x120 [libata]			
		? ata_host_alloc+0xf5/0x120 [libata]			
		? kfree+0x2cf/0x2f0			
CVE-2024-41087	Linux	ata_host_alloc+0xf5/0x120 [libata] ata_host_alloc_pinfo+0x14/0xa0 [libata]	2024-07-29	7.8	High
CVL-2024-4100/	LIIIUX	ata_nost_anot_pinio+ox14/oxao [iibata]	2024-07-23	7.0	ııığıı

	ahci_init_one+0x6c9/0xd20 [ahci]			
	Ensure that we will not call kfree(host) twice, by performing the kfree() only if the devres_open_group() call failed.			
	In the Linux kernel, the following vulnerability has been resolved:			
	drm/i915/gt: Fix potential UAF by revoke of fence registers			
	CI has been sporadically reporting the following issue triggered by igt@i915_selftest@live@hangcheck on ADL-P and similar machines:			
	<6> [414.049203] i915: Running intel_hangcheck_live_selftests/igt_reset_evict_fence			
	<6> [414.068812] i915 0000:00:02.0: [drm] GT0: GUC: SLPC enabled			
	<3> [414.070354] Unable to pin Y-tiled fence; err:-4 <3> [414.071282] i915_vma_revoke_fence:301 GEM_BUG_ON(!i915_active_is_idle(&fence->active))			
	 <4>[ 609.603992][ cut here ]			
	<pre>&lt;2&gt;[ 609.603995] kernel BUG at drivers/gpu/drm/i915/gt/intel_ggtt_fencing.c:301!</pre>			
	<4>[ 609.604003] invalid opcode: 0000 [#1] PREEMPT SMP NOPTI <4>[ 609.604006] CPU: 0 PID: 268 Comm: kworker/u64:3 Tainted:			
	G U W 6.9.0-CI_DRM_14785-g1ba62f8cea9c+ #1 <4>[ 609.604008] Hardware name: Intel Corporation Alder Lake			
	Client Platform/AlderLake-P DDR4 RVP, BIOS RPLPFWI1.R00.4035.A00.2301200723 01/20/2023 <4>[ 609.604010] Workqueue: i915i915 _gem_free_work [i915]			
	<pre>&lt;4&gt;[ 009.004010] Workquede: 19131913_getti_free_work [1913] &lt;4&gt;[ 609.604149] RIP: 0010:i915_vma_revoke_fence+0x187/0x1f0 [i915]</pre>			
	 <4>[ 609.604271] Call Trace: <4>[ 609.604273] <task></task>			
	 <4>[ 609.604716]i915_vma_evict+0x2e9/0x550 [i915]			
	<pre>&lt;4&gt;[ 609.604852]i915_vma_unbind+0x7c/0x160 [i915] &lt;4&gt;[ 609.604977] force_unbind+0x24/0xa0 [i915] &lt;4&gt;[ 609.605098] i915_vma_destroy+0x2f/0xa0 [i915]</pre>			
	<pre>&lt;4&gt;[ 609.605210]i915_gem_object_pages_fini+0x51/0x2f0 [i915] &lt;4&gt;[ 609.605330]i915_gem_free_objects.isra.0+0x6a/0xc0</pre>			
	[i915] <4>[ 609.605440] process_scheduled_works+0x351/0x690			
	In the past, there were similar failures reported by CI from other IGT			
	tests, observed on other platforms.			
	Before commit 63baf4f3d587 ("drm/i915/gt: Only wait for GPU activity			
	before unbinding a GGTT fence"), i915_vma_revoke_fence() was waiting for			
	idleness of vma->active via fence_update(). That commit introduced			
	vma->fence->active in order for the fence_update() to be able to wait			
	selectively on that one instead of vma->active since only idleness of			
	fence registers was needed. But then, another commit 0d86ee35097a			
	("drm/i915/gt: Make fence revocation unequivocal") replaced the call to			
	fence_update() in i915_vma_revoke_fence() with only fence_write(), and			
	also added that GEM_BUG_ON(!i915_active_is_idle(&fence->active)) in front.  No justification was provided on why we might then expect			
	idleness of vma->fence->active without first waiting on it.			
	The issue can be potentially caused by a race among revocation of			
<u>CVE-2024-41092</u> Linux	fence registers on one side and sequential execution of signal callbacks	2024-07-29	7.8	High

			T	ı	1
		invoked on completion of a request that was using them on the other, still processed in parallel to revocation of those fence registers. Fix it by waiting for idleness of vma->fence->active in			
		i915_vma_revoke_fence().  (cherry picked from commit 24bb052d3dd499c5956abad5f7d8e4fd07da7fb1)  In the Linux kernel, the following vulnerability has been resolved:			
		PCI/MSI: Fix UAF in msi_capability_init			
		KFENCE reports the following UAF:			
		BUG: KFENCE: use-after-free read inpci_enable_msi_range+0x2c0/0x488			
		Use-after-free read at 0x0000000024629571 (in kfence-#12):pci_enable_msi_range+0x2c0/0x488 pci_alloc_irq_vectors_affinity+0xec/0x14c pci_alloc_irq_vectors+0x18/0x28			
		kfence-#12: 0x000000008614900-0x00000000e06c228d, size=104, cache=kmalloc-128			
		allocated by task 81 on cpu 7 at 10.808142s:kmem_cache_alloc_node+0x1f0/0x2bc kmalloc_trace+0x44/0x138 msi_alloc_desc+0x3c/0x9c msi_domain_insert_msi_desc+0x30/0x78 msi_setup_msi_desc+0x13c/0x184pci_enable_msi_range+0x258/0x488 pci_alloc_irq_vectors_affinity+0xec/0x14c pci_alloc_irq_vectors+0x18/0x28			
		freed by task 81 on cpu 7 at 10.811436s: msi_domain_free_descs+0xd4/0x10c msi_domain_free_locked.part.0+0xc0/0x1d8 msi_domain_alloc_irqs_all_locked+0xb4/0xbc pci_msi_setup_msi_irqs+0x30/0x4cpci_enable_msi_range+0x2a8/0x488 pci_alloc_irq_vectors_affinity+0xec/0x14c pci_alloc_irq_vectors+0x18/0x28			
		Descriptor allocation done in:pci_enable_msi_range msi_capability_init msi_setup_msi_desc msi_insert_msi_desc msi_domain_insert_msi_desc msi_alloc_desc			
		Freed in case of failure inmsi_domain_alloc_locked()pci_enable_msi_range msi_capability_init pci_msi_setup_msi_irqs msi_domain_alloc_irqs_all_locked msi_domain_alloc_lockedmsi_domain_alloc_locked => fails msi_domain_free_locked			
		That failure propagates back to pci_msi_setup_msi_irqs() in msi_capability_init() which accesses the descriptor for unmasking in the error exit path.			
		Cure it by copying the descriptor and using the copy for the error exit path unmask operation.			
CVE-2024-41096	Linux	[ tglx: Massaged change log ]	2024-07-29	7.8	High
		In the Linux kernel, the following vulnerability has been resolved:			
		bpf: Fix may_goto with negative offset.  Zac's syzbot crafted a bpf prog that exposed two bugs in			
CVE-2024-42072	Linux	may_goto.	2024-07-29	7.8	High

		The 1st bug is the way may_goto is patched. When offset is negative it should be patched differently. The 2nd bug is in the verifier: when current state may_goto_depth is equal to visited state			
		may_goto_depth it means there is an actual infinite loop. It's not correct to prune exploration of the program at this point. Note, that this check doesn't limit the program to only one may_goto insn,			
		since 2nd and any further may_goto will increment may_goto_depth only in the queued state pushed for future exploration. The current state will have may_goto_depth == 0 regardless of number of may_goto			
		insns and the verifier has to explore the program until bpf_exit.			
CVE 2022 42059	Applo	A permissions issue was addressed with additional restrictions. This issue is fixed in macOS Ventura 13.4. An app may be able to	2024 07 20	7.0	∐igh
CVE-2023-42958	Apple	gain elevated privileges.  The issue was addressed with improved memory handling. This issue is fixed in macOS Ventura 13.6.8, macOS Sonoma 14.5, macOS Monterey 12.7.6, watchOS 10.5, visionOS 1.3, tvOS 17.5,	2024-07-29	7.8	High
CVE-2024-27826	Apple	iOS 17.5 and iPadOS 17.5. An app may be able to execute arbitrary code with kernel privileges.  An integer overflow was addressed with improved input validation. This issue is fixed in iOS 16.7.9 and iPadOS 16.7.9, macOS Ventura 13.6.8, iOS 17.6 and iPadOS 17.6, watchOS 10.6,	2024-07-29	7.8	High
CVE-2024-40784	Apple	tvOS 17.6, visionOS 1.3, macOS Sonoma 14.6. Processing a maliciously crafted file may lead to unexpected app termination.	2024-07-29	7.8	High
CVE-2024-40802	Apple	The issue was addressed with improved checks. This issue is fixed in macOS Sonoma 14.6, macOS Monterey 12.7.6, macOS Ventura 13.6.8. A local attacker may be able to elevate their privileges.	2024-07-29	7.8	High
		In the Linux kernel, the following vulnerability has been resolved:  scsi: mpi3mr: Sanitise num_phys			
CVE-2024-42159	Linux	Information is stored in mr_sas_port->phy_mask, values larger then size of this field shouldn't be allowed.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-30	7.8	High
CVE-2024-42160	Linux	f2fs: check validation of fault attrs in f2fs_build_fault_attr()  - It missed to check validation of fault attrs in parse_options(), let's fix to add check condition in f2fs_build_fault_attr().  - Use f2fs_build_fault_attr() insbi_store() to clean up code. In the Linux kernel, the following vulnerability has been resolved:	2024-07-30	7.8	High
		bpf: Avoid uninitialized value in BPF_CORE_READ_BITFIELD  [Changes from V1: - Use a default branch in the switch statement to initialize `val'.]			
		GCC warns that `val' may be used uninitialized in the BPF_CRE_READ_BITFIELD macro, defined in bpf_core_read.h as:			
		[] unsigned long long val; \ [] \			
		<pre>switch (CORE_RELO(s, field, BYTE_SIZE)) {   case 1: val = *(const unsigned char *)p; break;   case 2: val = *(const unsigned short *)p; break;   case 4: val = *(const unsigned int *)p; break;   case 8: val = *(const unsigned long long *)p; break;   }   []   val; \</pre>			
		This patch adds a default entry in the switch statement that sets 'val' to zero in order to avoid the warning, and random values to be used in casebuiltin_preserve_field_info returns unexpected values			
		for BPF_FIELD_BYTE_SIZE.  Tested in bpf-next master.			
CVE-2024-42161	Linux	No regressions.	2024-07-30	7.8	High

ı		Trans. 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		T	
		In the Linux kernel, the following vulnerability has been resolved:			
		net: dsa: mv88e6xxx: Correct check for empty list			
		Since commit a3c53be55c95 ("net: dsa: mv88e6xxx: Support multiple MDIO			
		busses") mv88e6xxx_default_mdio_bus() has checked that the return value of list_first_entry() is non-NULL.			
		This appears to be intended to guard against the list chip->mdios being			
		empty. However, it is not the correct check as the implementation of			
		list_first_entry is not designed to return NULL for empty lists.			
		Instead, use list_first_entry_or_null() which does return NULL if the list is empty.			
		Flagged by Smatch.			
CVE-2024-42224	Linux	Compile tested only.  Dell Peripheral Manager, versions prior to 1.7.6, contain an	2024-07-30	7.8	High
CVE-2024-32857	Dell	uncontrolled search path element vulnerability. An attacker could potentially exploit this vulnerability through preloading malicious DLL or symbolic link exploitation, leading to arbitrary code execution and escalation of privilege  Dell Peripheral Manager, versions prior to 1.7.6, contain an uncontrolled search path element vulnerability. An attacker could potentially exploit this vulnerability through preloading malicious DLL or symbolic link exploitation, leading to arbitrary code	2024-07-31	7.8	High
CVE-2024-37127	Dell	execution and escalation of privilege	2024-07-31	7.8	High
CVE-2024-37142	Dell	Dell Peripheral Manager, versions prior to 1.7.6, contain an uncontrolled search path element vulnerability. An attacker could potentially exploit this vulnerability through preloading malicious DLL or symbolic link exploitation, leading to arbitrary code execution and escalation of privilege  A vulnerability was reported in Lenovo PC Manager prior to	2024-07-31	7.8	High
0.45 0040 6407		version 2.8.90.11211 that could allow a local attacker to escalate	2024 07 24	7.0	
CVE-2019-6197	Lenovo	privileges.  A vulnerability was reported in Lenovo PC Manager prior to	2024-07-31	7.8	High
CVE-2019-6198	Lenovo	version 2.8.90.11211 that could allow a local attacker to escalate privileges.	2024-07-31	7.8	High
CVE-2023-1577	Lenovo	A path hijacking vulnerability was reported in Lenovo Driver Manager prior to version 3.1.1307.1308 that could allow a local user to execute code with elevated privileges.	2024-07-31	7.8	High
CVE-2024-39392	Adobe	InDesign Desktop versions ID18.5.2, ID19.3 and earlier are affected by a Heap-based Buffer Overflow vulnerability that could result in arbitrary code execution in the context of the current user. Exploitation of this issue requires user interaction in that a victim must open a malicious file.	2024-08-02	7.8	High
		A permissions issue was addressed with additional restrictions.  This issue is fixed in watchOS 10.6, macOS Sonoma 14.6, iOS 17.6 and iPadOS 17.6, tvOS 17.6. An app may be able to bypass Privacy			
CVE-2024-40805	Apple	preferences.	2024-07-29	7.7	High
CVE-2024-40824	Apple	This issue was addressed through improved state management. This issue is fixed in watchOS 10.6, macOS Sonoma 14.6, iOS 17.6 and iPadOS 17.6, tvOS 17.6. An app may be able to bypass Privacy preferences.	2024-07-29	7.7	High
		A logic issue was addressed with improved restrictions. This issue is fixed in macOS Sonoma 14.4. An unprivileged app may be able to log keystrokes in other apps including those using secure input			
CVE-2024-27886	Apple	mode.  The issue was addressed with improved checks. This issue is fixed in watchOS 10.6, iOS 17.6 and iPadOS 17.6, iOS 16.7.9 and iPadOS	2024-07-29	7.5	High
CVE-2024-40829	Apple	16.7.9, macOS Ventura 13.6.8. An attacker may be able to view restricted content from the lock screen.  A logic issue was addressed with improved checks. This issue is fixed in watchOS 10.6, macOS Sonoma 14.6, iOS 17.6 and iPadOS	2024-07-29	7.5	High
CVE-2024-40836	Apple	17.6, iOS 16.7.9 and iPadOS 16.7.9. A shortcut may be able to use sensitive data with certain actions without prompting the user.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-29	7.5	High
		wifi: mt76: replace skb_put with skb_put_zero			
CVE-2024-42225	Linux	Avoid potentially reusing uninitialized data	2024-07-30	7.5	High
		A permissions issue was addressed by removing vulnerable code and adding additional checks. This issue is fixed in macOS Sonoma 14.4. An app may be able to modify protected parts of the file			
CVE-2024-27888	Apple	system.	2024-07-29	7.1	High

		The issue was addressed with improved restriction of data container access. This issue is fixed in macOS Sonoma 14.6, macOS Monterey 12.7.6, macOS Ventura 13.6.8. A malicious application			
CVE-2024-40783	Apple	may be able to bypass Privacy preferences.  A downgrade issue was addressed with additional code-signing	2024-07-29	7.1	High
		restrictions. This issue is fixed in macOS Sonoma 14.6. An app may			
CVE-2024-40814	Apple	be able to bypass Privacy preferences.	2024-07-29	7.1	High
		Dell BSAFE Crypto-C Micro Edition 4.1.5 and Dell BSAFE Micro Edition Suite, versions 4.0 through 4.6.1 and version 5.0 contain a			
CVE-2023-28074	Dell	buffer over-read vulnerability.	2024-07-31	7.1	High
		A race condition was addressed with improved state handling. This			
CVE-2023-42959	Apple	issue is fixed in macOS Sonoma 14. An app may be able to execute arbitrary code with kernel privileges.	2024-07-29	7	High
011 2020 1200	7,6610	In the Linux kernel, the following vulnerability has been resolved:	20210723	,	
		gve: Account for stopped queues when reading NIC stats			
		We now account for the fact that the NIC might send us stats for a subset of queues. Without this change, gve_get_ethtool_stats might make			
CVE-2024-42162	Linux	an invalid access on the priv->stats_report->stats array.	2024-07-30	7	High
		In the Linux kernel, the following vulnerability has been resolved:			
		drm/amdgpu: Using uninitialized value *size when calling amdgpu_vce_cs_reloc			
		Initialize the size before calling amdgpu_vce_cs_reloc, such as case 0x03000001.			
CVE-2024-42228	Linux	V2: To really improve the handling we would actually need to have a separate value of 0xffffffff.(Christian)	2024-07-30	7	High
011201120		A vulnerability has been identified in Omnivise T3000 Application		-	
		Server (All versions). Affected devices allow authenticated users to			
		export diagnostics data. The corresponding API endpoint is susceptible to path traversal and could allow an authenticated			
CVE-2024-38878	Siemens	attacker to download arbitrary files from the file system.	2024-08-02	6.9	Medium
		Dell Inventory Collector, versions prior to 12.3.0.6 contains a Path			
CVE 2024 27420	Dell	Traversal vulnerability. A local authenticated malicious user could potentially exploit this vulnerability, leading to arbitrary code	2024 07 24	6.7	NA o di cons
CVE-2024-37129	Dell	execution on the system.  The issue was addressed with improved memory handling. This	2024-07-31	6.7	Medium
		issue is fixed in iOS 17 and iPadOS 17, macOS Sonoma 14, watchOS			
		10, tvOS 17. An app may be able to execute arbitrary code with			
CVE-2023-40396	Apple	kernel privileges. CloudLink, versions 7.1.x and 8.x, contain an Improper check or	2024-07-29	6.6	Medium
		handling of Exceptional Conditions Vulnerability in Cluster			
		Component. A highly privileged malicious user with remote access			
		could potentially exploit this vulnerability, leading to execute unauthorized actions and retrieve sensitive information from the			
CVE-2024-38482	Dell	database.	2024-08-02	6.6	Medium
		A buffer overflow issue was addressed with improved memory			
		handling. This issue is fixed in macOS Sonoma 14.6. An app with			
CVE-2024-27878	Apple	root privileges may be able to execute arbitrary code with kernel privileges.	2024-07-29	6.5	Medium
CVL-2024-27878	Арріе	IBM Aspera Orchestrator 4.0.1 is vulnerable to cross-site request	2024-07-23	0.5	ivieulum
		forgery which could allow an attacker to execute malicious and			
CVE 2022 28001	IDA4	unauthorized actions transmitted from a user that the website trusts. IBM X-Force ID: 260206.	2024 07 20	6.5	Madium
CVE-2023-38001	IBM	The issue was addressed with improved memory handling. This	2024-07-30	6.5	Medium
		issue is fixed in macOS Sonoma 14.6, macOS Monterey 12.7.6,			
		macOS Ventura 13.6.8. Processing a maliciously crafted file may			
CVE-2024-27877	Apple	lead to a denial-of-service or potentially disclose memory contents.	2024-07-29	6.1	Medium
CVE-2024-27877	Арріе	Dell InsightIQ, Verion 5.0.0, contains a use of a broken or risky	2024-07-29	0.1	ivieuluiii
		cryptographic algorithm vulnerability. An unauthenticated remote			
CVE 2024 20072	Dell	attacker could potentially exploit this vulnerability, leading to	2024 00 01	F 0	Madium
CVE-2024-28972	Dell	In the Linux kernel, the following vulnerability has been resolved:	2024-08-01	5.9	Medium
		ASoC: SOF: Intel: hda: fix null deref on system suspend entry			
		When system enters suspend with an active stream, SOF core			
		calls hw_params_upon_resume(). On Intel platforms with HDA DMA used			
		to manage the link DMA, this leads to call chain of			
		hda_dsp_set_hw_params_upon_resume() -> hda_dsp_dais_suspend()			
		-> hda_dai_suspend() -> hda_dai_suspend()			
CVE-2024-41037	Linux	-> hda_ipc4_post_trigger()	2024-07-29	5.5	Medium

A bug is the Indust, bit. Journal of the Community of the						
una first. which clears had, stream-blink, substream, and then had spirk, pont, risigent) is called with a Nutura beam substream pointer. In the survival karned, the following whereholdly has been recoved:  firmware: cs, digs. Prevent buffer overant when processing V2 alls headers Check that all fields of a V2 algorithm header fit into the available firmware data buffer.  The wrift V2 format introduced variable-length strings in the algorithm. Book header: This means the overall header freight strings in the algorithm. Book writes depending on the length of the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string fields: Each field must be checked to ensure that it does not the string field must be checked to ensure that it does not the checked that it does not			A bug is hit in hda dai suspend() as hda link dma cleanup() is			
in the Linux kernell, the following vulnerability has been resolved:  In the Linux kernell, the following vulnerability has been resolved:  In the Linux kernell, the following vulnerability has been resolved:  It immers co. drips Prevent buffer overrun when processing V2 alla leaders.  Check that all fields of a V2 algorithm header fit into the available immers data buffer.  The unrive V2 format introduced variable-length strings in the algorithm block header. This means the overall header length is variable, and the position of most fields varies depending on the length of the string fields. Such field must be checked to ensure that it does not need the position of most fields varies depending on the length of the string fields. Such field must be checked to ensure that it does not need the immers of the transport of the transport of the creating fields. Such field must be checked to ensure that it does not need the immers of the transport of						
h to be the with a NULL and, pero, substrain pointer.  In the Linux kernet, the following volunerability has been resolved:  Item waves cs_dop Prevent buffer overrun when proussing V2 dight headers.  Check that all fields of a V2 algorithm header fit into the available firmware data buffer.  The wind V2 format introduced variable-length strings in the algorithm block header. This means the overall header length is variable, and position of most fields varies depending on the heritath of the string fields. Facilified must be checked to ensure that it does not over flaw the firmware data buffer.  As this is bugfer, buffer, buffer with the checked to ensure that it does not over flaw the firmware data buffer.  As this is bugfer, buffer, buffer with the fill wind the string fields. Facilified for the properties of the checked to ensure that it does not over flaw the fill wind the properties of the prope						
In the Linux kernel, the following vulnerability has been resolved: firmwarts ca, dispi Prevent buffer overrun when processing V2 allg headers  Check that all fields of a V2 algorithm header fit into the available firmware data buffer.  The wmfw V2 formal introduced variable length strings in the algorithm block header. This means the overall header length is variable, and the firmware data buffer.  As this is buglis patch, the fixers ovoid making any significant change to the firmware data buffer.  As this is buglis patch, the fixers ovoid making any significant change to the firmware data buffer.  As this is buglis patch, the fixers ovoid making any significant change to the revisiting code. This makes it easier to review and less filedy to introduce new bugs.  It must burned the firm and patient develorence in mv2 T_v_wet_hd_mode(s), the return value of dirm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer configure of firm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer configure of firm_mode_duplicate() in the fluxe kernel, the following vulnerability has been resolved: drm/nowabuffer in the fluxe kernel, the following vulnerability has been resolved: drm/nowabuffer by calling orm_gem_fb_get_boli) and return error code when object is must be check to avoid null pointer dereference in the fluxe kernel, the following vulnerability has been resolved: drm/ambebuffer by calling orm_gem_fb_get_boli) and return error code when object is must be checked to avoid uping null object of framebuffer in the fluxe kernel, the following vulnerability has been resolved: drm/counce_duplicate() is assigned to mode, duplicate() in the fluxe kernel, the following vulnerability has been resolved: drm. mode, duplicate() is assigned to mode, duplicate() is assigned to mode, duplicate() is assigned to mod			= · = · = · · ·			
headers Check that all fields of a V2 algorithm header fit into the available firmware data buffer.  The work V7 formal introduced variable length strings in the algorithm block header. This means the overall header length is variable, and the position of most fields varias depending on the length of the string fields. Each field must be checked to ensure that it does not over time to the timeware data buffer.  As this is bugiffs patch, the fixes avoid making any significant change to the ensiting code. This makes it eacher to review and less likely to introduce new but bus.  CVE 2024.41038 Umax  Limux						
headers Check that all fields of a V2 algorithm header fit into the available firmware data buffer.  The worky V7 format introduced variable length strings in the algorithm block header. This means the overall header length is variable, and the position of most fields varies depending on the length of the string fields. Each field must be checked to ensure that it does not over flow the firmware data buffer.  As this is bugiffs patch, the fises avoid making any significant change to the eisting code. This makes it eader to review and less likely to introduce new but bus.  OVE 2024.41038 Umus  Limus  In the Limus kernel, the following vulnerability has been resolved:  drm/novesu/disprvdd-fix fix rull pointer dereference in m27.17, yet. Jul modes.  In m22.17, yet. Jul modes.  In m22.19, yet. Jul modes.  In m22.19, yet. Jul modes.  In m22.19, yet. Jul modes.  In the Limus kernel, the following vulnerability has been resolved:  drm/novesu/disprvd of unit pointer dereference.  In the Limus kernel, the following vulnerability has been resolved:  drm/amdgps: avoid using null object of framebuffer  Instead of using state-M2-bodi(0) directly, get object from framebuffer by calling drm. gern. Jo. yet. obj(1) and return error code when object is not time kernel, the following vulnerability has been resolved:  drm/novesu/disprvd-fix froull pointer dereference in m22.19, yet. Jul modes.  In m22.19, yet. Jul modes.  In the time kernel, the following vulnerability has been resolved:  drm/novesu/disprvd-fix froull pointer dereference on a error.  If the ata_port_alloct[ call in ata_hod_alloct] fails, atu host_release() will yet called.  However, the code in ata_hod_release() fire to reference on a error.  If the ata_port_alloct[ call in ata_hod_alloct] fails, atu host_release() will yet called.  However, the code in ata_hod_release() fire to reference on a error.  If the ata_port_alloct[ call in ata_hod_alloct] fails, atu host_release() will ye						
firmware data buffer.  The wmfw V2 formal introduced variable-length strings in the algorithm black header. This means the overall header length is variable, and prosition of most fields and the checked to ensure that it does not overflow the firmware data buffer.  As this is bugfit patch, the fixes avoid making any significant (change to the length of the string fields. Fash field must be checked to ensure that it does not overflow the fixes as the string one. The fixes a solid making any significant (change to the existing code. This makes it easier to review and less likely to the existing code. This makes it easier to review and less likely to introduce new bugs.  In the timus kernel, the following vulnerability has been resolved:  In middle of the fixes and						
algorithm bitok header. This means the overall header length is variable, and the position of most fields varies depending on the length of the string fields. Each field must be checked to ensure that it does not overflow the firmware data buffer.  As this is longfix patch, the flues avoid making any significant change to goods. This makes it easier to review and less likely to introduce new buss.  In the Limux kernet, the following vulnerability has been resolved: dm//nouveau/dispn/04: fix null pointer dereference in nu17_tv_get_hd_modes In nu17_tv_get_hd_modes. In nu17_tv_get_hd_modes. In nu17_tv_get_hd_modes. In nu17_tv_get_hd_modes. In nu17_tv_get_hd_modes. In nu17_tv_get_hd_modes. In the Limux kernet, the following vulnerability has been resolved: dr//m_mode_duplicate(): The same applies to dr//m_mode_duplicate(): The same applies to dr//m_mode_duplicate(): The same applies to dr//m_comeduplicate(): The same applies to framebuffer linstead of using state->hb-obj[o] directly, get object from famebuffer by calling drm/geem_fo_spet_obj[o] directly, get object from famebuffer by calling drm/geem_fo_spet_object of framebuffer.  2024-07-29 5.55 Medium In the Limux kernet, the following vulnerability has been resolved: drm//nouveau/dispn/04: fix null pointer dereference in nu17_tv_get_ld_modes In null to avoid using null object of framebuffer.  2024-07-29 5.55 Medium In the Limux kernet, the following vulnerability has been resolved: dr//m_mode_duplicate(): The same applies to free ata_port struct members unconditionally, which can lead to the follo			_			
the position of most fields varies depending on the length of the string fields. Each field must be checked to ensure that it does not overflow the firmware data buffer.  As the la bugfix patch, the fives avoid making any significant change to the existing code. This makes it easier to review and less likely to increduce new bugs.  In the timux levenel, the following vulnerability has been resolved: dim/noveau/dispn/d4. fix null pointer dereference in nv17_v get_hd_modes). The return value of dim_mode_uplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). The same applies to drm_cvt_mode(). Add a check to avoid null pointer dereference.  OVE-2024-41089 Linux Add a check to avoid null pointer dereference.  In the Linux kernel, the following vulnerability has been resolved: drm/amdgpu: avoid using null object of framebuffer.  In the Linux kernel, the following vulnerability has been resolved: drm/amdgpu: avoid using null object of framebuffer.  In the Linux kernel, the following vulnerability has been resolved: drm/noweau/dispn/d4: fix null pointer dereference in nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes(), the return error code when object is null to avoid using null object of framebuffer.  In the Linux kernel, the following vulnerability has been resolved: drm/noweau/dispn/d4: fix null pointer dereference in nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer on filling of drm, mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer on filling of drm, mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer on filling of drm, mode_duplicate() had a check to avoid npd.  Linux on failure of drm, mode_duplicate(). Add a check to avoid npd.  He has port_allor() call in ata_host_allor() fails, ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  Bugs_unable to handle			algorithm			
fields. Sach field must be checked to ensure that it does not overflow the firmware data buffer.  As this is bugfix patch, the fixes avoid making any significant change to the existing code. This makes it easier to review and less likely to introduce new bugs.  In the Linux kernel, the following vulnerability has been resolved: drm/nouveau/dapm04; fix null pointer dereference in mv3.7 to yet, the modes in nv1.7 to yet, he mode which will lead to a possible NULL pointer dereference on foliure of drm, mode, duplicately. The same applies to confoliure of drm, mode, which will lead to a possible NULL pointer dereference.  In the Linux kernel, the following vulnerability has been resolved: drm/amdgpu: avoid using null object of framebuffer  Instead of using state-offs-obj() directly, get object from framebuffer by calling drm yem, fb yet, obj() and return error code when objects in the Linux kernel, the following vulnerability has been resolved: drm/nouveau/dispov04; fix null pointer dereference in nv1.7 to yet, ld_modes in the Linux kernel, the following vulnerability has been resolved: drm/nouveau/dispov04; fix null pointer dereference in nv1.7 to yet, ld_mode yet, and will lead to a possible NULL pointer dereference in nv1.7 to yet, ld_mode yet, and will lead to a possible NULL pointer dereference in nv1.7 to yet, ld_mode yet, and yet in the Linux kernel, the following vulnerability has been resolved: ata: libato-core: Fix null pointer dereference on error if the sta, port, pointer of mm mode duplicately. Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved: ata: libato-core: Fix null pointer dereference on error if the sta, port, pointer of mm mode duplicately. Add a check to avoid npd.  In the Linux kernel, the following vulnerability has be			the			
As this is bugfix patch, the fixes avoid making any significant change to the existing code. This makes it easier to review and less likely to introduce new bugs.  In the lunux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in nv17_rv_get_hd_modes), the return value of drm mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm condition of the provided of the pr			fields. Each field must be checked to ensure that it does not overflow			
change to the existing code. This makes it easier to review and less likely to introduce new bugs.  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispmodi-fix null pointer dereference in m/17_bu_get_hd_modes(). The return value of drm mode, duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm mode, duplicate(). The same applies to drm control of drm. contr						
introduce new bugs.  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In he Linux kernel, the following vulnerability has been resolved:  In nv17_tv_get_hd_modes    In nv17_tv_get_hd_modes    In nv17_tv_get_hd_modes    In nv17_tv_get_hd_modes    In nv17_tv_get_hd_modes    In nv17_tv_get_hd_mode    In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In the Linux kernel, the following vulnerability has been resolved:  In			change to			
drm/nouveau/dispnv04; fix null pointer dereference in nv17_tv_get_hd_modes   In nv18_tv_mode   In the Linux kernet, the following vulnerability has been resolved:  drm/amdgpu: avoid using null object of framebuffer Instead of using state->fb->obj(0) directly, get object from framebuffer by calling drm_gem_fb_get_object of framebuffer Vu calling drm_gem_fb_get_object of framebuffer In the Linux kernet, the following vulnerability has been resolved:  drm/nouveau/dispnv04: ftx null pointer dereference in nv17_tv_get_ld_modes   In nv17_	CVE-2024-41038	Linux	introduce new bugs.	2024-07-29	5.5	Medium
In nv17_tv_get_hd_modes  In nv17_tv_get_hd_modes  In nv17_tv_get_hd_modes  In nv17_tv_get_hd_modes  It nv27_tv_get_hd_modes  It nv27_tv_get_ld_modes  It nv27_tv_dest_ld; is assigned to mode, which will lead to a possible NULL pointer dereference on Fallare of drm_mode_duplicate(). The same applies to drm_cvt_mode().  Add a check to avoid null pointer dereference.  In the Linux kernel, the following vulnerability has been resolved:  drm/amdbuffer  by calling drm_gem_fb_get_ob() and return error code when object is  null to avoid using null object of framebuffer.  CVE-2024-41093  Linux  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in  nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes  In the Linux kernel, the following vulnerability has been resolved:  dereference  on failure of drm mode_duplicate(). Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails,  ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port  struct  members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990  PG0 0 P40 0  Opps: Opps: 0000 [ft1] PREEMPT SMP NOPTI  CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44  Hardware name: (QEMU Standard PC (i440PCx P INt, 1996), BIOS  11.63 = 21c40 = 40/12/2 = 20c4 =			in the Linux kerner, the following vulnerability has been resolved:			
drm, mode, duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm, mode _duplicate(). The same applies to drm_cvt_mode(). Add a check to avoid null pointer dereference.    In the Linux kernel, the following vulnerability has been resolved:						
assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm, mode_duplicate(). The same applies to drm_cve_mode().  Add a check to avoid null pointer dereference.  In the Linux kernel, the following vulnerability has been resolved:  drm/amdgpu: avoid using null object of framebuffer  Instead of using state>fb>ob[[0] directly, get object from framebuffer  by calling drm_gem_fb_get_obj() and return error code when object is  unit to avoid using null object of framebuffer.  2024-07-29  5.5 Medium  VE-2024-41093  Linux  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in  nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct  members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PGD 0 PdD 0 Opps: 00ps: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.1.0.0-rc5 #44 Hardware name. CBMU standard PC (440FX + PINX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010-rata_host_release.cold+0x2f70x6e [libata] Code: e4 ad 63 ft 44 88 e 2 48 C7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41  RSP: 0010-rata_host_release.cold+0x2f70x6e [libata] Code: e4 ad 63 ft 44 88 e 2 48 C7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41  RSP: 0010-rata_host_release.cold+0x2f70x6e [libata] Code: e4 ad 63 ft 44 88 e2 48 C7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41						
dereference on failure of drm_mode_duplicate(). The same applies to drm_cvt_mode().  Add a check to avoid null pointer dereference.  In the Linux kernel, the following vulnerability has been resolved:  drm/amdgpu: avoid using null object of framebuffer  Instead of using state>fb>obj[0] directly, get object from framebuffer by calling drm_gem_fb_get_obj() and return error code when object is null to avoid using null object of framebuffer.  VE-2024-41093 Linux null to avoid using null object of framebuffer.  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm mode_duplicate(). Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PciD 0 PciD 0 PciD 0 Oops: 0000 [fi1] PREEMPT SMP NOPTI CPU: 10 PliD: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: CgMU Standard Pci (l440FX + PliX, 1996), BIOS 1.16.3-2 fcaQ 04/01/2014 RIP: 0010-ata_bost_release cold+bx2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 67 c7 d0 70 03 c0 48 83 c 60 e41  RIP: 0010-ata_bost_release cold+bx2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 67 c7 d0 70 03 c0 48 83 c6 0e 41  RIP: 0010-ata_bost_release cold+bx2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 67 c7 d0 70 03 c0 48 83 c6 0e 41  RIP: 0010-ata_bost_release cold+bx2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 03 c0 48 83 c6 0e 41			= = ' "			
drm_cvt_mode(). Add acheck to avoid null pointer dereference. In the Linux kernel, the following vulnerability has been resolved:  drm/amdgpu: avoid using null object of framebuffer  linstead of using state->fb->obj(0) directly, get object from framebuffer by calling drm_gem_fb_get_obj() and return error code when object is null to avoid using null object of framebuffer.  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in nv17_tv_get_id_modes  In the Linux kernel, the following vulnerability has been resolved: ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct  members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 00000000000003990 PGD 0 P4D 0 Ops; 00ps: 0000 (#1) PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: 6EMU Standard PC (1440Fx PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:sata_host_release cold+0x2/f0x6e (libata) Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RP: 0010:sita_host_release cold+0x2/f0x6e (libata)			dereference			
Linux Add a check to avoid null pointer dereference.    2024-07-29   5.5   Medium						
In the Linux kernel, the following vulnerability has been resolved:  drm/amdgpu: avoid using null object of framebuffer  linstead of using state->fb->obj[0] directly, get object from framebuffer by calling drm_gem_fb_get_obj() and return error code when object is null to avoid using null object of framebuffer.  2024-07-29 5.5 Medium  In the Linux kernel, the following vulnerability has been resolved: drm/nouveau/dispnv04: fix null pointer dereference in nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved: ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PGD 0 P4D 0 Ops: 00ps: 00ps: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comms; (udev-worker) trained 6.10.0-rc5 #44 Hardware name: CBMU Standard PC (#440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010-3ta_host_release cold+0x2f/0x6e [libata] Code: e4 4 d6 3f 4 4 48 9e 2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:fffics0000ebb968 EFLAGS: 00010246	CVE-2024-41089	Linux		2024-07-29	5.5	Medium
Instead of using state->fb->obj[0] directly, get object from framebuffer by calling drm_gem_fb_get_obj() and return error code when object is null to avoid using null object of framebuffer. 2024-07-29 5.5 Medium  Linux null to avoid using null object of framebuffer. 2024-07-29 5.5 Medium  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in nv17_tv_get_id_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of fram_mode_duplicate(). Add a check to avoid npd. 2024-07-29 5.5 Medium  In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000000390 PGD 0 PAD 0  Opps: Opps: 0000 [#1] PREEMPT SMP NOPTI  CPU: 10 PID: 594 Comm: (udex-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014  RIP: 0010:ata_host_release(oid+0x2f/0x6e [libata] Code: et 4d 63 ft 4d 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41  RSP: 0010:8tff(90000ebb968 EFLAGS: 00010246			,			
framebuffer by calling drm_gem_fb_get_obj() and return error code when object is null to avoid using null object of framebuffer.  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in nv17_tv_get_ld_modes;  ln nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of frm_mode_duplicate(). Add a check to avoid npd.  Linux linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 00000000000003990 PGD 0 P4D 0  Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI  CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014  RIP: 0010-ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41  RSP: 0018-fff:690000ebb968 EFLAGS: 00010246			drm/amdgpu: avoid using null object of framebuffer			
by calling drm_gem_fb_get_obj() and return error code when object is null to avoid using null object of framebuffer. 2024-07-29 5.5 Medium  In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). Add a check to avoid npd. 2024-07-29 5.5 Medium  In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 00000000000000000990 PGD 0 P4D 0  Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI  CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014  RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata]  Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 48 3 c6 0e 41  RSP: 0018:ffffc50000ebb968 EFLAGS: 00010246						
Linux   null to avoid using null object of framebuffer.   2024-07-29   5.5   Medium			by calling drm_gem_fb_get_obj() and return error code when			
In the Linux kernel, the following vulnerability has been resolved:  drm/nouveau/dispnv04: fix null pointer dereference in nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes  In nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved: ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PGD 0 P4D 0 Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: 0EMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 67 c6 90 ad 32 c0 48 67 c7 d0 70 33 c0 49 83 c0 e41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246	CVF-2024-41093	Linux		2024-07-29	5.5	Medium
nv17_tv_get_id_modes  In nv17_tv_get_id_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). Add a check to avoid npd. 2024-07-29  In the Linux kernel, the following vulnerability has been resolved: ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 000000000003990 PGD 0 P4D 0 Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 66 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246	<u> </u>	Lindx		20210723	3.3	Wicaram
In nv17_tv_get_ld_modes(), the return value of drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PGD 0 P4D 0  Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI  CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014  RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41  RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246						
drm_mode_duplicate() is assigned to mode, which will lead to a possible NULL pointer dereference on failure of drm_mode_duplicate(). Add a check to avoid npd.  In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 00000000000003990 PGD 0 P4D 0  Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI  CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014  RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata]  Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41  RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246						
dereference on failure of drm_mode_duplicate(). Add a check to avoid npd. In the Linux kernel, the following vulnerability has been resolved: ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PGD 0 P4D 0 Oops: Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 48 9e 248 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246			drm_mode_duplicate() is			
In the Linux kernel, the following vulnerability has been resolved:  ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails,  ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port  struct  members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990  PGD 0 P4D 0   Oops: 0000 [#1] PREEMPT SMP NOPTI   CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44   Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS   1.16.3-2.fc40 04/01/2014   RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata]   Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33   c0 49 83 c6 0e 41   RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246						
ata: libata-core: Fix null pointer dereference on error  If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 00000000000003990 PGD 0 P4D 0  Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246	CVE-2024-41095	Linux		2024-07-29	5.5	Medium
If the ata_port_alloc() call in ata_host_alloc() fails, ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 00000000000003990 PGD 0 P4D 0  Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246			In the Linux kernel, the following vulnerability has been resolved:			
ata_host_release() will get called.  However, the code in ata_host_release() tries to free ata_port struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 00000000000003990 PGD 0 P4D 0  Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014  RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246			ata: libata-core: Fix null pointer dereference on error			
struct members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PGD 0 P4D 0 Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246						
members unconditionally, which can lead to the following:  BUG: unable to handle page fault for address: 0000000000003990 PGD 0 P4D 0 Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246						
PGD 0 P4D 0 Oops: Oops: 0000 [#1] PREEMPT SMP NOPTI CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246						
CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS 1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246			. •			
1.16.3-2.fc40 04/01/2014 RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246			CPU: 10 PID: 594 Comm: (udev-worker) Not tainted 6.10.0-rc5 #44			
RIP: 0010:ata_host_release.cold+0x2f/0x6e [libata] Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246			•			
Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33 c0 49 83 c6 0e 41 RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246						
RSP: 0018:ffffc90000ebb968 EFLAGS: 00010246			Code: e4 4d 63 f4 44 89 e2 48 c7 c6 90 ad 32 c0 48 c7 c7 d0 70 33			
CVL-2024-41036 EIIIdA NAA. 000000000000001 NBA. IIII888101B32E78 NCA. 2024-07-23 3.5 Wiedidiii	CVE-2024-41098	Linux	RAX: 000000000000041 RBX: ffff88810fb52e78 RCX:	2024-07-29	5.5	Medium

		1	1	1	T 1
		00000000000000000000000000000000000000			
		RBP: ffff88810fb52e40 R08: 00000000000000 R09: 6c65725f74736f68			
		R10: ffffc90000ebb738 R11: 73692033203a746e R12: 000000000000004			
		R13: 000000000000 R14: 00000000000011 R15: 00000000000006			
		FS: 00007f6cc55b9980(0000) GS:ffff88813b300000(0000)			
		knlGS:000000000000000000000000000000000000			
		CR2: 000000000003990 CR3: 00000001122a2000 CR4: 000000000750ef0			
		PKRU: 5555554 Call Trace:			
		<task> ?die_body.cold+0x19/0x27</task>			
		? page_fault_oops+0x15a/0x2f0 ? exc_page_fault+0x7e/0x180			
		? asm_exc_page_fault+0x26/0x30 ? ata_host_release.cold+0x2f/0x6e [libata]			
		? ata_host_release.cold+0x2f/0x6e [libata] release_nodes+0x35/0xb0			
		devres_release_group+0x113/0x140 ata_host_alloc+0xed/0x120 [libata]			
		ata_nost_anoc+0xed/0x120 [nbata] ata_host_alloc_pinfo+0x14/0xa0 [libata] ahci_init_one+0x6c9/0xd20 [ahci]			
		Do not access ata_port struct members unconditionally.  In the Linux kernel, the following vulnerability has been resolved:			
		drm/amd/display: Skip pipe if the pipe idx not set properly			
		[why] Driver crashes when pipe idx not set properly			
CVE-2024-42064	Linux	[how] Add code to skip the pipe that idx not set properly In the Linux kernel, the following vulnerability has been resolved:	2024-07-29	5.5	Medium
		drm/xe: Add a NULL check in xe_ttm_stolen_mgr_init			
CVE 2024 420CE	Limense		2024.07.20		Madium
CVE-2024-42065	Linux	Add an explicit check to ensure that the mgr is not NULL.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-29	5.5	Medium
		drm/xe: Fix potential integer overflow in page size calculation			
CVE-2024-42066	Linux	Explicitly cast tbo->page_alignment to u64 before bit-shifting to prevent overflow when assigning to min_page_size.	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		<pre>bpf: Take return from set_memory_rox() into account with bpf_jit_binary_lock_ro()</pre>			
		set_memory_rox() can fail, leaving memory unprotected.			
CVE-2024-42067	Linux	Check return and bail out when bpf_jit_binary_lock_ro() returns an error.	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		<pre>bpf: Take return from set_memory_ro() into account with bpf_prog_lock_ro()</pre>			
		set_memory_ro() can fail, leaving memory unprotected.			
CVE-2024-42068	Linux	Check its return and take it into account as an error.	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:  net: mana: Fix possible double free in error handling path			
		When auxiliary_device_add() returns error and then calls auxiliary_device_uninit(), callback function adev_release			
CVE-2024-42069	Linux	calls kfree(madev). We shouldn't call kfree(madev) again in the error handling path. Set 'madev' to NULL.	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		netfilter: nf_tables: fully validate NFT_DATA_VALUE on store to data registers			
<u>CVE-2024-42070</u>	Linux		2024-07-29	5.5	Medium

		register store validation for NET DATA MALLIE is as additional			
		register store validation for NFT_DATA_VALUE is conditional, however, the datatype is always either NFT_DATA_VALUE or			
		NFT_DATA_VERDICT. This only requires a new helper function to infer the register type from			
		the set datatype so this conditional check can be removed. Otherwise,			
		pointer to chain object can be leaked through the registers.  In the Linux kernel, the following vulnerability has been resolved:			
		ionic: use dev_consume_skb_any outside of napi			
		If we're not in a NAPI softirq context, we need to be careful about how we call napi_consume_skb(), specifically we need to call it with budget==0 to signal to it that we're not in a safe context.			
		This was found while running some configuration stress testing of traffic and a change queue config loop running, and this curious note popped out:			
		[ 4371.402645] BUG: using smp_processor_id() in preemptible [00000000] code: ethtool/20545 [ 4371.402897] caller is napi_skb_cache_put+0x16/0x80 [ 4371.403120] CPU: 25 PID: 20545 Comm: ethtool Kdump: loaded Tainted: G OE 6.10.0-rc3-netnext+ #8 [ 4371.403302] Hardware name: HPE ProLiant DL360 Gen10/ProLiant DL360 Gen10, BIOS U32 01/23/2021 [ 4371.403460] Call Trace: [ 4371.403613] <task></task>			
		[ 4371.403013] CTASK2 [ 4371.403758] dump_stack_lvl+0x4f/0x70 [ 4371.403904] check_preemption_disabled+0xc1/0xe0 [ 4371.404051] napi_skb_cache_put+0x16/0x80 [ 4371.404199] ionic_tx_clean+0x18a/0x240 [ionic] [ 4371.404354] ionic_tx_cq_service+0xc4/0x200 [ionic] [ 4371.404505] ionic_tx_flush+0x15/0x70 [ionic] [ 4371.404653] ? ionic_lif_qcq_deinit.isra.23+0x5b/0x70 [ionic] [ 4371.404805] ionic_txrx_deinit+0x71/0x190 [ionic] [ 4371.404956] ionic_reconfigure_queues+0x5f5/0xff0 [ionic] [ 4371.405111] ionic_set_ringparam+0x2e8/0x3e0 [ionic] [ 4371.405265] ethnl_set_rings+0x1f1/0x300 [ 4371.405418] ethnl_default_set_doit+0xbb/0x160 [ 4371.405571] genl_family_rcv_msg_doit+0xff/0x130 []			
		I found that ionic_tx_clean() calls napi_consume_skb() which calls napi_skb_cache_put(), but before that last call is the note  /* Zero budget indicate non-NAPI context called us, like netpoll  */ and			
		DEBUG_NET_WARN_ON_ONCE(!in_softirq());  Those are pretty hig hints that we're doing it wrong. We can pass			
		Those are pretty big hints that we're doing it wrong. We can pass a context hint down through the calls to let ionic_tx_clean() know			
CVE-2024-42071	Linux	what we're doing so it can call napi_consume_skb() correctly.	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		mlxsw: spectrum_buffers: Fix memory corruptions on Spectrum-4 systems			
		The following two shared buffer operations make use of the Shared Buffer Status Register (SBSR):			
		# devlink sb occupancy snapshot pci/0000:01:00.0 # devlink sb occupancy clearmax pci/0000:01:00.0			
		The register has two masks of 256 bits to denote on which ingress			
		egress ports the register should operate on. Spectrum-4 has more than			
		256 ports, so the register was extended by cited commit with a new			
		'port_page' field.			
		However, when filling the register's payload, the driver specifies the			
CVE-2024-42073	Linux	ports as absolute numbers and not relative to the first port of the	2024-07-29	5.5	Medium

1		Ι.	1		1
		port page, resulting in memory corruptions [1].			
		Fix by specifying the ports relative to the first port of the port			
		page.			
		[1] BUG: KASAN: slab-use-after-free in			
		mlxsw_sp_sb_occ_snapshot+0xb6d/0xbc0 Read of size 1 at addr ffff8881068cb00f by task devlink/1566			
		[]			
		Call Trace: <task></task>			
		dump_stack_lvl+0xc6/0x120			
		print_report+0xce/0x670 kasan_report+0xd7/0x110			
		mlxsw_sp_sb_occ_snapshot+0xb6d/0xbc0 mlxsw_devlink_sb_occ_snapshot+0x75/0xb0			
		devlink_nl_sb_occ_snapshot_doit+0x1f9/0x2a0			
		genl_family_rcv_msg_doit+0x20c/0x300 genl_rcv_msg+0x567/0x800			
		netlink_rcv_skb+0x170/0x450			
		genl_rcv+0x2d/0x40 netlink_unicast+0x547/0x830			
		netlink_sendmsg+0x8d4/0xdb0 sys_sendto+0x49b/0x510			
		x64_sys_sendto+0xe5/0x1c0			
		do_syscall_64+0xc1/0x1d0 entry_SYSCALL_64_after_hwframe+0x77/0x7f			
		[] Allocated by task 1:			
		kasan_save_stack+0x33/0x60			
		kasan_save_track+0x14/0x30 kasan_kmalloc+0x8f/0xa0			
		copy_verifier_state+0xbc2/0xfb0 do_check_common+0x2c51/0xc7e0			
		bpf_check+0x5107/0x9960			
		bpf_prog_load+0xf0e/0x2690 sys_bpf+0x1a61/0x49d0			
		x64_sys_bpf+0x7d/0xc0			
		do_syscall_64+0xc1/0x1d0 entry_SYSCALL_64_after_hwframe+0x77/0x7f			
		Freed by task 1:			
		kasan_save_stack+0x33/0x60			
		kasan_save_track+0x14/0x30 kasan_save_free_info+0x3b/0x60			
		poison_slab_object+0x109/0x170 kasan_slab_free+0x14/0x30			
		kfree+0xca/0x2b0			
		free_verifier_state+0xce/0x270 do_check_common+0x4828/0xc7e0			
		bpf_check+0x5107/0x9960 bpf_prog_load+0xf0e/0x2690			
		sys_bpf+0x1a61/0x49d0			
		x64_sys_bpf+0x7d/0xc0 do_syscall_64+0xc1/0x1d0			
		entry_SYSCALL_64_after_hwframe+0x77/0x7f  In the Linux kernel, the following vulnerability has been resolved:			
		ASoC: amd: acp: add a null check for chip_pdev structure			
		When acp platform device creation is skipped, chip->chip_pdev value will			
CVE 2024 42074	Linux	remain NULL. Add NULL check for chip->chip_pdev structure in	2024 07 20		Madium
CVE-2024-42074	Linux	snd_acp_resume() function to avoid null pointer dereference.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-29	5.5	Medium
		bpf: Fix remap of arena.			
		The bpf arena logic didn't account for mremap operation. Add a refcnt for multiple mmap events to prevent use-after-free in			
CVE-2024-42075	Linux	arena_vm_close.	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:  net: can: j1939: Initialize unused data in j1939_send_one()			
CVE-2024-42076	Linux	syzbot reported kernel-infoleak in raw_recvmsg() [1]. j1939_send_one()	2024-07-29	5.5	Medium
	<del></del>				

	1		1	1
	creates full frame including unused data, but it doesn't initialize it. This causes the kernel-infoleak issue. Fix this by initializing unused data.			
	[1]			
	BUG: KMSAN: kernel-infoleak in instrument_copy_to_user include/linux/instrumented.h:114 [inline]			
	BUG: KMSAN: kernel-infoleak in copy_to_user_iter			
	lib/iov_iter.c:24 [inline] BUG: KMSAN: kernel-infoleak in iterate ubuf			
	include/linux/iov_iter.h:29 [inline]			
	BUG: KMSAN: kernel-infoleak in iterate_and_advance2 include/linux/iov_iter.h:245 [inline]			
	BUG: KMSAN: kernel-infoleak in iterate_and_advance			
	include/linux/iov_iter.h:271 [inline] BUG: KMSAN: kernel-infoleak in _copy_to_iter+0x366/0x2520			
	lib/iov_iter.c:185			
	instrument_copy_to_user include/linux/instrumented.h:114			
	[inline] copy_to_user_iter lib/iov_iter.c:24 [inline]			
	iterate_ubuf include/linux/iov_iter.h:29 [inline]			
	<pre>iterate_and_advance2 include/linux/iov_iter.h:245 [inline] iterate_and_advance include/linux/iov_iter.h:271 [inline]</pre>			
	_copy_to_iter+0x366/0x2520 lib/iov_iter.c:185			
	copy_to_iter include/linux/uio.h:196 [inline] memcpy_to_msg include/linux/skbuff.h:4113 [inline]			
	raw_recvmsg+0x2b8/0x9e0 net/can/raw.c:1008			
	sock_recvmsg_nosec net/socket.c:1046 [inline] sock_recvmsg+0x2c4/0x340 net/socket.c:1068			
	sys_recvmsg+0x18a/0x620 net/socket.c:2803			
	sys_recvmsg+0x223/0x840 net/socket.c:2845			
	do_recvmmsg+0x4fc/0xfd0 net/socket.c:2939sys_recvmmsg net/socket.c:3018 [inline]			
	do_sys_recvmmsg net/socket.c:3041 [inline]			
	se_sys_recvmmsg net/socket.c:3034 [inline]x64_sys_recvmmsg+0x397/0x490 net/socket.c:3034			
	x64_sys_call+0xf6c/0x3b50			
	arch/x86/include/generated/asm/syscalls_64.h:300 do_syscall_x64 arch/x86/entry/common.c:52 [inline]			
	do_syscall_64+0xcf/0x1e0 arch/x86/entry/common.c:83			
	entry_SYSCALL_64_after_hwframe+0x77/0x7f			
	Uninit was created at:			
	slab_post_alloc_hook mm/slub.c:3804 [inline]			
	slab_alloc_node mm/slub.c:3845 [inline] kmem_cache_alloc_node+0x613/0xc50 mm/slub.c:3888			
	kmalloc_reserve+0x13d/0x4a0 net/core/skbuff.c:577			
	alloc_skb+0x35b/0x7a0 net/core/skbuff.c:668 alloc_skb include/linux/skbuff.h:1313 [inline]			
	alloc_skb_with_frags+0xc8/0xbf0 net/core/skbuff.c:6504			
	sock_alloc_send_pskb+0xa81/0xbf0 net/core/sock.c:2795 sock_alloc_send_skb include/net/sock.h:1842 [inline]			
	j1939_sk_alloc_skb net/can/j1939/socket.c:878 [inline]			
	j1939_sk_send_loop net/can/j1939/socket.c:1142 [inline] j1939_sk_sendmsg+0xc0a/0x2730 net/can/j1939/socket.c:1277			
	sock_sendmsg_nosec net/socket.c:730 [inline]			
	sock_sendmsg+0x30f/0x380 net/socket.c:745			
	sys_sendmsg+0x877/0xb60 net/socket.c:2584 sys_sendmsg+0x28d/0x3c0 net/socket.c:2638			
	sys_sendmsg net/socket.c:2667 [inline]			
	do_sys_sendmsg net/socket.c:2676 [inline]se_sys_sendmsg net/socket.c:2674 [inline]			
	x64_sys_sendmsg+0x307/0x4a0 net/socket.c:2674			
	x64_sys_call+0xc4b/0x3b50 arch/x86/include/generated/asm/syscalls_64.h:47			
	do_syscall_x64 arch/x86/entry/common.c:52 [inline]			
	do_syscall_64+0xcf/0x1e0 arch/x86/entry/common.c:83 entry_SYSCALL_64_after_hwframe+0x77/0x7f			
	Bytes 12-15 of 16 are uninitialized  Memory access of size 16 starts at ffff888120969690			
	Data copied to user address 0000000200017c0			
	CDII: 1 DID: 5050 Comm: svz. ovocutor100 Not tointed 6.0.0 mg			
	CPU: 1 PID: 5050 Comm: syz-executor198 Not tainted 6.9.0-rc5-syzkaller-00031-g71b1543c83d6 #0			
	Hardware name: Google Google Compute Engine/Google Compute			
	Engine, BIOS Google 03/27/2024  In the Linux kernel, the following vulnerability has been resolved:			
CVE 2024 42077		2024.07.55		na - !
<u>CVE-2024-42077</u> Linux	ocfs2: fix DIO failure due to insufficient transaction credits	2024-07-29	5.5	Medium

		The code in ocfs2_dio_end_io_write() estimates number of necessary			
		transaction credits using ocfs2_calc_extend_credits(). This however does			
		not take into account that the IO could be arbitrarily large and can contain arbitrary number of extents.			
		Extent tree manipulations do often extend the current transaction but not			
		in all of the cases. For example if we have only single block extents			
		the tree, ocfs2_mark_extent_written() will end up calling ocfs2_replace_extent_rec() all the time and we will never extend			
		the current transaction and eventually exhaust all the transaction credits if			
		the IO contains many single block extents. Once that happens a WARN_ON(jbd2_handle_buffer_credits(handle) <= 0) is triggered			
		jbd2_journal_dirty_metadata() and subsequently OCFS2 aborts in response to			
		this error. This was actually triggered by one of our customers on a			
		heavily fragmented OCFS2 filesystem.			
		To fix the issue make sure the transaction always has enough credits for			
		one extent insert before each call of ocfs2_mark_extent_written().  Heming Zhao said:			
		PANIC: "Kernel panic - not syncing: OCFS2: (device dm-1): panic forced after error"			
		PID: xxx TASK: xxxx CPU: 5 COMMAND: "SubmitThread-CA" #0 machine_kexec at ffffffff8c069932			
		#1crash_kexec at fffffff8c1338fa #2 panic at fffffff8c1d69b9			
		#3 ocfs2_handle_error at fffffffc0c86c0c [ocfs2] #4ocfs2_abort at fffffffc0c88387 [ocfs2]			
		#5 ocfs2_journal_dirty at fffffffc0c51e98 [ocfs2] #6 ocfs2_split_extent at fffffffc0c27ea3 [ocfs2]			
		#7 ocfs2_change_extent_flag at ffffffffc0c28053 [ocfs2] #8 ocfs2_mark_extent_written at fffffffc0c28347 [ocfs2]			
		#9 ocfs2_dio_end_io_write at fffffffc0c2bef9 [ocfs2]			
		#10 ocfs2_dio_end_io at ffffffffc0c2c0f5 [ocfs2] #11 dio_complete at ffffffff8c2b9fa7			
		#12 do_blockdev_direct_IO at fffffff8c2bc09f #13 ocfs2_direct_IO at fffffffc0c2b653 [ocfs2]			
		#14 generic_file_direct_write at fffffff8c1dcf14			
		#15generic_file_write_iter at ffffffff8c1dd07b #16 ocfs2_file_write_iter at fffffffc0c49f1f [ocfs2]			
		#17 aio_write at fffffff8c2cc72e #18 kmem_cache_alloc at fffffff8c248dde			
		#19 do_io_submit at fffffff8c2ccada			
		#20 do_syscall_64 at fffffff8c004984 #21 entry_SYSCALL_64_after_hwframe at fffffff8c8000ba			
		In the Linux kernel, the following vulnerability has been resolved:  nfsd: initialise nfsd_info.mutex early.			
		nfsd_info.mutex can be dereferenced by svc_pool_stats_start()			
		immediately after the new netns is created. Currently this can trigger an oops.			
CVE-2024-42078	Linux	Move the initialisation earlier before it can possibly be dereferenced.	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:  gfs2: Fix NULL pointer dereference in gfs2_log_flush			
		In gfs2_jindex_free(), set sdp->sd_jdesc to NULL under the log			
		flush lock to provide exclusion against gfs2_log_flush().			
		In gfs2_log_flush(), check if sdp->sd_jdesc is non-NULL before dereferencing it. Otherwise, we could run into a NULL pointer			
CVE-2024-42079	Linux	dereference when outstanding glock work races with an unmount	2024-07-29	5.5	Medium

		(glock_work_func -> run_queue -> do_xmote -> inode_go_sync -> gfs2_log_flush).  In the Linux kernel, the following vulnerability has been resolved:			
		RDMA/restrack: Fix potential invalid address access			
		struct rdma_restrack_entry's kern_name was set to KBUILD_MODNAME in ib_create_cq(), while if the module exited but forgot del this rdma_restrack_entry, it would cause a invalid address access in rdma_restrack_clean() when print the owner of this			
		rdma_restrack_entry.			
		These code is used to help find one forgotten PD release in one of the			
CVE-2024-42080	Linux	ULPs. But it is not needed anymore, so delete them.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-29	5.5	Medium
		drm/xe/xe_devcoredump: Check NULL before assignments			
		Assign 'xe_devcoredump_snapshot *' and 'xe_device *' only if 'coredump' is not NULL.			
		v2 - Fix commit messages.			
		v3 - Define variables before code.(Ashutosh/Jose)			
		v4 - Drop return check for coredump_to_xe. (Jose/Rodrigo)			
CVE-2024-42081	Linux	v5 - Modify misleading commit message. (Matt)	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		xdp: Remove WARN() fromxdp_reg_mem_model()			
		syzkaller reports a warning inxdp_reg_mem_model().			
		The warning occurs only ifmem_id_init_hash_table() returns an error. It returns the error in two cases:			
		<ol> <li>memory allocation fails;</li> <li>rhashtable_init() fails when some fields of rhashtable_params struct are not initialized properly.</li> </ol>			
		The second case cannot happen since there is a static const rhashtable_params struct with valid fields. So, warning is only triggered when there is			
		a problem with memory allocation.			
		Thus, there is no sense in using WARN() to handle this error and it			
		can be safely removed.			
		WARNING: CPU: 0 PID: 5065 at net/core/xdp.c:299xdp_reg_mem_model+0x2d9/0x650 net/core/xdp.c:299			
		CPU: 0 PID: 5065 Comm: syz-executor883 Not tainted 6.8.0-syzkaller-05271-gf99c5f563c17 #0 Hardware name: Google Google Compute Engine, BIOS Google 03/27/2024 RIP: 0010:xdp_reg_mem_model+0x2d9/0x650 net/core/xdp.c:299			
		Call Trace:  xdp_reg_mem_model+0x22/0x40 net/core/xdp.c:344  xdp_test_run_setup net/bpf/test_run.c:188 [inline]  bpf_test_run_xdp_live+0x365/0x1e90 net/bpf/test_run.c:377  bpf_prog_test_run_xdp+0x813/0x11b0 net/bpf/test_run.c:1267  bpf_prog_test_run+0x33a/0x3b0 kernel/bpf/syscall.c:4240 sys_bpf+0x48d/0x810 kernel/bpf/syscall.c:5649 do_sys_bpf kernel/bpf/syscall.c:5738 [inline]  _se_sys_bpf kernel/bpf/syscall.c:5736 [inline]  _x64_sys_bpf+0x7c/0x90 kernel/bpf/syscall.c:5736			
CVE-2024-42082	Linux	do_syscall_64+0xfb/0x240 entry SYSCALL 64 after hwframe+0x6d/0x75	2024-07-29	5.5	Medium
OVE 2027 72002	LIIIUA	Shary_Stashine_or_arter_nwiraline toxou/ 0x/3	2027 UI-ZJ	٥.٥	.vicaiaiii

Г	<u> </u>				1
		Found by Linux Verification Center (linuxtesting.org) with syzkaller.			
		In the Linux kernel, the following vulnerability has been resolved:			
		ionic: fix kernel panic due to multi-buffer handling			
	I	Currently, the ionic_run_xdp() doesn't handle multi-buffer packets			
		properly for XDP_TX and XDP_REDIRECT.			
	I	When a jumbo frame is received, the ionic_run_xdp() first makes			
		rame with all necessary pages in the rx descriptor.			
		And if the action is either XDP_TX or XDP_REDIRECT, it should			
		unmap			
		dma-mapping and reset page pointer to NULL for all pages, not			
		only the first page.			
		But it doesn't for SG pages. So, SG pages unexpectedly will be			
		reused.			
		It eventually causes kernel panic.			
		Oops: general protection fault, probably for non-canonical address			
		0x504f4e4dbebc64ff: 0000 [#1] PREEMPT SMP NOPTI			
		CPU: 3 PID: 0 Comm: swapper/3 Not tainted 6.10.0-rc3+ #25			
		RIP: 0010:xdp_return_frame+0x42/0x90			
		Code: 01 75 12 5b 4c 89 e6 5d 31 c9 41 5c 31 d2 41 5d e9 73 fd ff ff			
		44 8b 6b 20 0f b7 43 0a 49 81 ed 68 01 00 00 49 29 c5 49 01 fd <41> 80 7d0			
		RSP: 0018:ffff99d00122ce08 EFLAGS: 00010202			
		RAX: 00000000005453 RBX: ffff8d325f904000 RCX:			
		000000000000001 RDX: 0000000670e1000 RSI: 000000011f90d000 RDI:			
	I	504f4e4d4c4b4a49			
	I	RBP: ffff99d003907740 R08: 00000000000000 R09:			
		00000000000000			
	I	R10: 000000011f90d000 R11: 00000000000000 R12: ffff8d325f904010			
	I	R13: 504f4e4dbebc64fd R14: ffff8d3242b070c8 R15:			
		ffff99d0039077c0			
	I	FS: 0000000000000000(0000) GS:ffff8d399f780000(0000)			
	I	knlGS:000000000000000000000000000000000000			
		CR2: 00007f41f6c85e38 CR3: 000000037ac30000 CR4:			
	I	0000000007506f0			
	I	PKRU: 5555554			
		Call Trace: <irq></irq>			
		? die_addr+0x33/0x90			
		? exc_general_protection+0x251/0x2f0			
		? asm_exc_general_protection+0x22/0x30			
		? xdp_return_frame+0x42/0x90 ionic_tx_clean+0x211/0x280 [ionic			
		15881354510e6a9c655c59c54812b319ed2cd015]			
		ionic_tx_cq_service+0xd3/0x210 [ionic			
		15881354510e6a9c655c59c54812b319ed2cd015] ionic_txrx_napi+0x41/0x1b0 [ionic			
		15881354510e6a9c655c59c54812b319ed2cd015]			
	I	napi_poll.constprop.0+0x29/0x1b0			
	I	net_rx_action+0x2c4/0x350			
		handle_softirqs+0xf4/0x320 irq_exit_rcu+0x78/0xa0			
CVE-2024-42083	Linux	common_interrupt+0x77/0x90	2024-07-29	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
	I	in a constitution of the state			
	I	i2c: pnx: Fix potential deadlock warning from del_timer_sync() call in isr			
		When del_timer_sync() is called in an interrupt context it throws a			
		warning			
		because of potential deadlock. The timer is used only to exit from wait_for_completion() after a timeout so replacing the call with			
		wait_for_completion_timeout() allows to remove the problematic			
01/5 202 1 15 1 5 5		timer and	2024 27 55		
<u>CVE-2024-42153</u>	Linux	its related functions altogether.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-30	5.5	Medium
		The Linux Reffici, the following vulnerability has been resolved.			
		media: dvb-frontends: tda10048: Fix integer overflow			
		state->xtal_hz can be up to 16M, so it can overflow a 32 bit integer			
CVE-2024-42223	Linux	when multiplied by pll_mfactor.	2024-07-30	5.5	Medium
			1 1 1 1		1

Г		T			1
		Create a new 64 bit variable to hold the calculations.  In the Linux kernel, the following vulnerability has been resolved:			
		btrfs: zoned: fix calc_available_free_space() for zoned mode			
		calc_available_free_space() returns the total size of metadata (or system) block groups, which can be allocated from unallocated disk			
		space. The logic is wrong on zoned mode in two places.			
		First, the calculation of data_chunk_size is wrong. We always allocate			
		one zone as one chunk, and no partial allocation of a zone. So, we should use zone_size (= data_sinfo->chunk_size) as it is.			
		Second, the result "avail" may not be zone aligned. Since we always			
		allocate one zone as one chunk on zoned mode, returning non- zone size			
		aligned bytes will result in less pressure on the async metadata reclaim			
		process.			
		This is serious for the nearly full state with a large zone size device.  Allowing over-commit too much will result in less async reclaim work and			
CVE-2024-42231	Linux	end up in ENOSPC. We can align down to the zone size to avoid that.	2024-07-30	5.5	Medium
		IBM Aspera Orchestrator 4.0.1 does not invalidate session after a password change which could allow an authenticated user to	<del>-</del>		
CVE-2023-26288	IBM	impersonate another user on the system. IBM X-Force ID: 248477.	2024-07-30	5.5	Medium
		Acrobat for Edge versions 126.0.2592.81 and earlier are affected by an out-of-bounds read vulnerability that could lead to arbitrary			
		file system read access. An attacker could exploit this vulnerability to read contents from a location in memory past the buffer			
		boundary, potentially leading to sensitive information disclosure.  Exploitation of this issue requires user interaction in that a victim			
CVE-2024-39379	Adobe	must open a malicious file.  A vulnerability was reported in Lenovo PC Manager versions prior	2024-07-31	5.5	Medium
CVE-2017-3772	Lenovo	to 2.6.40.3154 that could allow an attacker to cause a system reboot.	2024-07-31	5.5	Medium
		InDesign Desktop versions ID18.5.2, ID19.3 and earlier are affected by an out-of-bounds read vulnerability that could lead to			
		disclosure of sensitive memory. An attacker could leverage this vulnerability to bypass mitigations such as ASLR. Exploitation of			
CVE-2024-39396	Adobe	this issue requires user interaction in that a victim must open a malicious file.	2024-08-02	5.5	Medium
<u>CVL-2024-33330</u>	Adobe	IBM Aspera Orchestrator 4.0.1 is vulnerable to HTTP header	2024-00-02	3.3	Wediam
		injection, caused by improper validation of input by the HOST headers. This could allow an attacker to conduct various attacks			
CVE-2023-26289	IBM	against the vulnerable system, including cross-site scripting, cache poisoning or session hijacking. IBM X-Force ID: 248478.	2024-07-30	5.4	Medium
		A logic issue was addressed with improved state management. This issue is fixed in macOS Sonoma 14.6. Enabling Lockdown			
CVE-2024-27862	Apple	Mode while setting up a Mac may cause FileVault to become unexpectedly disabled.	2024-07-29	5.3	Medium
		** UNSUPPORTED WHEN ASSIGNED ** A vulnerability was found in D-Link DIR-600 up to 2.18. It has been rated as critical. This issue			
		affects the function soapcgi_main of the file /soap.cgi. The manipulation of the argument service leads to os command			
		injection. The attack may be initiated remotely. The exploit has been disclosed to the public and may be used. The identifier VDB-			
		273329 was assigned to this vulnerability. NOTE: This vulnerability only affects products that are no longer supported by the			
		maintainer. NOTE: Vendor was contacted early and confirmed			
CVE-2024-7357	D-Link	immediately that the product is end-of-life. It should be retired and replaced.	2024-08-01	5.3	Medium
		IBM Business Automation Workflow 22.0.2, 23.0.1, 23.0.2, and 24.0.0 stores potentially sensitive information in log files under			
CVE-2024-38321	IBM	certain situations that could be read by an authenticated user.  IBM X-Force ID: 284868.	2024-08-03	5.3	Medium
		A vulnerability, which was classified as critical, has been found in D-Link DI-8100 16.07. This issue affects the function msp_info_htm			
		of the file msp_info.htm. The manipulation of the argument cmd leads to command injection. The attack may be initiated remotely.			
CVE-2024-7436	D-Link	The exploit has been disclosed to the public and may be used. The identifier VDB-273521 was assigned to this vulnerability.	2024-08-03	5.3	Medium
<u> </u>	D LIIIK	1.55	202 1 00 03	J.J	,caiaiii

		In the Linux kernel, the following and a self-the head of the linux kernel.			
		In the Linux kernel, the following vulnerability has been resolved:			
		nvmet: fix a possible leak when destroy a ctrl during qp establishment			
		In nvmet_sq_destroy we capture sq->ctrl early and if it is non- NULL we			
		know that a ctrl was allocated (in the admin connect request handler)			
		and we need to release pending AERs, clear ctrl->sqs and sq->ctrl (for nvme-loop primarily), and drop the final reference on the ctrl.			
		However, a small window is possible where nvmet_sq_destroy			
		starts (as a result of the client giving up and disconnecting) concurrently with			
		the nyme admin connect cmd (which may be in an early stage).  But *before*			
		kill_and_confirm of sq->ref (i.e. the admin connect managed to get an sq			
		live reference). In this case, sq->ctrl was allocated however after it was			
		captured in a local variable in nvmet_sq_destroy. This prevented the final reference drop on the ctrl.			
		Solve this by re-capturing the sq->ctrl after all inflight request has completed, where for sure sq->ctrl reference is final, and move			
		forward based on that.			
		This issue was observed in an environment with many hosts			
CVE-2024-42152	Linux	connecting multiple ctrls simoutanuosly, creating a delay in allocating a ctrl leading up to this race window.	2024-07-30	4.7	Medium
CVL 2024 42132	Lillax	In the Linux kernel, the following vulnerability has been resolved:	2024 07 30	7.7	Wicaram
		drm/amd/display: Fix overlapping copy within dml_core_mode_programming			
		[WHY]			
		&mode_lib->mp.Watermark and &locals->Watermark are the same address. memcpy may lead to unexpected behavior.			
CVE-2024-42227	Linux	[HOW] memmove should be used.	2024-07-30	4.7	Medium
		Zohocorp ManageEngine Applications Manager versions 170900 and below are vulnerable to the authenticated admin-only SQL			
CVE-2024-5678	ManageEngine	Injection in the Create Monitor feature.  In the Linux kernel, the following vulnerability has been resolved:	2024-08-01	4.7	Medium
		usb: xhci: prevent potential failure in handle_tx_event() for Transfer events without TRB			
		Some transfer events don't always point to a TRB, and			
		consequently don't have a endpoint ring. In these cases, function handle_tx_event()			
		should not proceed, because if 'ep->skip' is set, the pointer to the			
		endpoint ring is used.			
		To prevent a potential failure and make the code logical, return after			
CVE-2024-42226	Linux	checking the completion code for a Transfer event without TRBs.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-30	4.6	Medium
		powerpc/pseries: Fix scv instruction crash with kexec			
		kexec on pseries disables AIL (reloc_on_exc), required for scv instruction support, before other CPUs have been shut down. This			
		they can execute scv instructions after AIL is disabled, which			
		interrupt at an unexpected entry location that crashes the kernel.			
		Change the kexec sequence to disable AIL after other CPUs have been brought down.			
CVE-2024-42230	Linux	As a refresher, the real-mode scv interrupt vector is 0x17000, and	2024-07-30	4.4	Medium
CAT 7074-45720	LIIIUA	1 / 5 & remestion, the real mode sev interrupt vector is 0x17000, and		1	IVICUIUIII

		the fixed-location head code probably couldn't easily deal with			
		implementing such high addresses so it was just decided not to support that			
		interrupt at all.			
		Dell iDRAC Service Module version 5.3.0.0 and prior, contain an Out of bound Read Vulnerability. A privileged local attacker could			
CVE-2024-25947	Dell	execute arbitrary code potentially resulting in a denial of service event.	2024-08-01	4.4	Medium
CVL-2024-23347	Deli	Dell iDRAC Service Module version 5.3.0.0 and prior, contain a Out	2024-08-01	4.4	ivieuluiii
		of bound Write Vulnerability. A privileged local attacker could			
CVE-2024-25948	Dell	execute arbitrary code potentially resulting in a denial of service event.	2024-08-01	4.4	Medium
		Dell iDRAC Service Module version 5.3.0.0 and prior, contain a Out			
		of bound Read Vulnerability. A privileged local attacker could execute arbitrary code potentially resulting in a denial of service			
CVE-2024-38481	Dell	event.	2024-08-01	4.4	Medium
		Dell iDRAC Service Module version 5.3.0.0 and prior contains Out of bound write Vulnerability. A privileged local attacker could			
		execute arbitrary code potentially resulting in a denial of service			
CVE-2024-38489	Dell	(partial) event.  Dell iDRAC Service Module version 5.3.0.0 and prior, contain a Out	2024-08-01	4.4	Medium
		of bound Write Vulnerability. A privileged local attacker could			
CVE-2024-38490	Dell	execute arbitrary code potentially resulting in a denial of service event.	2024-08-01	4.4	Medium
CVE-2024-38490	Deli	In the Linux kernel, the following vulnerability has been resolved:	2024-06-01	4.4	Mediuii
		s390/pkey: Wipe copies of clear-key structures on failure			
6) (5, 2024, 424.56		Wipe all sensitive data from stack for all IOCTLs, which convert a	2024 07 20		
CVE-2024-42156	Linux	clear-key into a protected- or secure-key.  In the Linux kernel, the following vulnerability has been resolved:	2024-07-30	4.1	Mediun
		,			
		s390/pkey: Wipe sensitive data on failure			
CVE-2024-42157	Linux	Wipe sensitive data from stack also if the copy_to_user() fails.	2024-07-30	4.1	Mediun
		In the Linux kernel, the following vulnerability has been resolved:			
		s390/pkey: Use kfree_sensitive() to fix Coccinelle warnings			
		Deployer represent a combinity) and before () with before a consitive() to			
		Replace memzero_explicit() and kfree() with kfree_sensitive() to fix			
		warnings reported by Coccinelle:			
		WARNING opportunity for kfree_sensitive/kvfree_sensitive (line			
		1506)			
		WARNING opportunity for kfree_sensitive/kvfree_sensitive (line 1643)			
C) /F 2024 424F0		WARNING opportunity for kfree_sensitive/kvfree_sensitive (line	2024 07 20	4.4	S A II -
CVE-2024-42158	Linux	1770) In the Linux kernel, the following vulnerability has been resolved:	2024-07-30	4.1	Medium
		crypto: aead,cipher - zeroize key buffer after use			
		I.G 9.7.B for FIPS 140-3 specifies that variables temporarily holding			
		cryptographic information should be zeroized once they are no longer			
		needed. Accomplish this by using kfree_sensitive for buffers that			
CVE-2024-42229	Linux	previously held the private key.  IBM Security Directory Integrator 7.2.0 and IBM Security Verify	2024-07-30	4.1	Medium
		Directory Integrator 10.0.0 could allow a remote attacker to obtain			
		sensitive information, caused by the failure to set the HTTPOnly flag. A remote attacker could exploit this vulnerability to obtain			
CVE-2022-33167	IBM	sensitive information from the cookie. IBM X-Force ID: 228587.	2024-07-30	3.7	Low
		An out-of-bounds access issue was addressed with improved			
		bounds checking. This issue is fixed in iOS 17.6 and iPadOS 17.6, watchOS 10.6, tvOS 17.6, visionOS 1.3, macOS Sonoma 14.6.			
		Processing a maliciously crafted file may lead to unexpected app			
CVE-2024-40777	Apple	termination.  DM5500 5.16.0.0, contains an information disclosure vulnerability.	2024-07-29	3.3	Low
		A local attacker with high privileges could potentially exploit this			
		vulnerability, leading to the disclosure of certain user credentials.  The attacker may be able to use the exposed credentials to access			
		the vulnerable application with privileges of the compromised			
CVE-2024-37135	Dell	account.	2024-07-31	3.3	Low
		In the Linux kernel, the following vulnerability has been resolved:			
CVE-2024-42155	Linux	s390/pkey: Wipe copies of protected- and secure-keys	2024-07-30	1.9	Low

Although the clear-key of neither protected- nor secure-keys is accessible, this key material should only be visible to the calling		
process. So wipe all copies of protected- or secure-keys from stack, even in case of an error.		

وحيث تقدم الهيئة تفاصيل الثغرات كما تم نشرها من قبل NIST's دوإذ تبقى NIST's وإذ تبقى التعراق كما تم نشرها من قبل NIST's NVD. In addition, it is the entity's or individual's responsibility to ensure the implementation of appropriate recommendations.