

تمت مشاركة هذه المعلومة بإشارة مشاركة \*\*\*أبيض\*\*\* حيث يسمح بتبادلها Please note that this notification/advisory has been tagged as TLP \*\*\*WHITE\*\*\* where information can be shared or published on any public forums.

أو نشرها من خلال القنوات العامة.

في ضوء دور الهيئة الوطنية للأمن السيبراني للمساعدة في حماية الفضاء As part of NCA duties to help securing the cyberspace and protecting السيبراني الوطني، تود الهيئة مشاركتكم النشرة الأسبوعية للتُغرات المسجلة national interests, NCA provides the weekly summary of published vulnerabilities by the National Institute of Standards and Technology the National Institute of Standards and Technology (NIST) من قبل (NIST) National Vulnerability Database (NVD) for the week from 18<sup>th</sup> راك عم National Vulnerability Database (NVD) of August to  $24^{th}$  of August. Vulnerabilities are scored using the Common أغسطس. علماً أنه يتم تصنيف هذه الثغرات باستخدام معيار Common Vulnerability Scoring System (CVSS) standard as per the حيث يتم تصنيف الثغرات بناء على Vulnerability Scoring System (CVSS) following severity:

Critical: CVSS base score of 9.0-10.0 High: CVSS base score of 7.0-8.9 Medium: CVSS base score 4.0-6.9 Low: CVSS base score 0.0-3.9

التالي:

عالى جدًا: النتيجة الأساسية لـCVSS 9.0-10.0

عالى: النتيجة الأساسية لـ8.9-7.0 CVSS

متوسط: النتيجة الأساسية لـ6.9-CVSS 4.0

منخفض: النتيجة الأساسية لـ CVSS 0.0-3.9

CVE ID & Source	Vendor - Product	Description	Publish Date	CVSS Score	Severity
		Hertzbeat is an open source, real-time monitoring system. Hertzbeat 1.6.0 and earlier declares a /api/monitor/{monitorId}/metric/{metricFull} endpoint to download job metrics. In the process, it executes a SQL query with			
CVE-2024-42361	Apache	user-controlled data, allowing for SQL injection.	2024-08-20	9.8	Critical
CVE 2024 20475	Missassft	An improper access control vulnerability in the Azure Managed Instance for Apache Cassandra allows an authenticated attacker to	2024 00 20	0.6	Cuitinal
CVE-2024-38175	Microsoft	elevate privileges over a network.  The SolarWinds Web Help Desk (WHD) software is affected by a	2024-08-20	9.6	Critical
		hardcoded credential vulnerability, allowing remote unauthenticated user to access internal functionality and modify			
CVE-2024-28987	SolarWinds	data.	2024-08-21	9.1	Critical
		Hertzbeat is an open source, real-time monitoring system. Hertzbeat has an authenticated (user role) RCE via unsafe deserialization in /api/monitors/import. This vulnerability is fixed			
CVE-2024-42362	Apache	in 1.6.0.  NETGEAR ProSAFE Network Management System getSortString	2024-08-20	8.8	High
		SQL Injection Remote Code Execution Vulnerability. This vulnerability allows remote attackers to execute arbitrary code on affected installations of NETGEAR ProSAFE Network Management System. Authentication is required to exploit this vulnerability.			
CV5 2024 C912	NETGEAR	The specific flaw exists within the getSortString method. The issue results from the lack of proper validation of a user-supplied string before using it to construct SQL queries. An attacker can leverage this vulnerability to execute code in the context of SYSTEM. Was ZDI-CAN-23207.	2024-08-21	8.8	I I i ala
<u>CVE-2024-6813</u>	NEIGEAR	NETGEAR ProSAFE Network Management System getFilterString SQL Injection Remote Code Execution Vulnerability. This vulnerability allows remote attackers to execute arbitrary code on affected installations of NETGEAR ProSAFE Network Management System. Authentication is required to exploit this vulnerability.  The specific flaw exists within the getFilterString method. The issue results from the lack of proper validation of a user-supplied string before using it to construct SQL queries. An attacker can	2024-06-21	0.0	High
CVE 2024 6914	NETGEAR	leverage this vulnerability to execute code in the context of SYSTEM. Was ZDI-CAN-23399.	2024-08-21	8.8	Uiah
<u>CVE-2024-6814</u>		Use after free in Passwords in Google Chrome on Android prior to 128.0.6613.84 allowed a remote attacker to potentially exploit heap corruption via a crafted HTML page. (Chromium security	2024-06-21		High
CVE-2024-7964	Google	severity: High)	2024-08-21	8.8	High
		Inappropriate implementation in V8 in Google Chrome prior to 128.0.6613.84 allowed a remote attacker to potentially exploit heap corruption via a crafted HTML page. (Chromium security			
CVE-2024-7965	Google	severity: High)	2024-08-21	8.8	High
CVE-2024-7966	Google	Out of bounds memory access in Skia in Google Chrome prior to 128.0.6613.84 allowed a remote attacker who had compromised	2024-08-21	8.8	High

		the renderer process to perform out of bounds memory access via a crafted HTML page. (Chromium security severity: High)  Heap buffer overflow in Fonts in Google Chrome prior to			
		128.0.6613.84 allowed a remote attacker to potentially exploit heap corruption via a crafted HTML page. (Chromium security			
CVE-2024-7967	Google	severity: High)	2024-08-21	8.8	High
		Use after free in Autofill in Google Chrome prior to 128.0.6613.84 allowed a remote attacker who had convinced the user to engage			
CVE-2024-7968	Google	in specific UI interactions to potentially exploit heap corruption via a crafted HTML page. (Chromium security severity: High)	2024-08-21	8.8	⊔iah
CVE-2024-7908	Google	Type Confusion in V8 in Google Chrome prior to 128.0.6613.113	2024-08-21	0.0	High
		allowed a remote attacker to potentially exploit heap corruption			
CVE-2024-7969	Google	via a crafted HTML page. (Chromium security severity: High)	2024-08-21	8.8	High
		Type confusion in V8 in Google Chrome prior to 128.0.6613.84			
CVE-2024-7971	Google	allowed a remote attacker to exploit heap corruption via a crafted HTML page. (Chromium security severity: High)	2024-08-21	8.8	High
CVE-2024-7971	Google	Inappropriate implementation in V8 in Google Chrome prior to	2024-06-21	0.0	півіі
		128.0.6613.84 allowed a remote attacker to potentially perform			
		out of bounds memory access via a crafted HTML page.			
CVE-2024-7972	Google	(Chromium security severity: Medium)	2024-08-21	8.8	High
		Heap buffer overflow in PDFium in Google Chrome prior to			
		128.0.6613.84 allowed a remote attacker to perform an out of bounds memory read via a crafted PDF file. (Chromium security			
CVE-2024-7973	Google	severity: Medium)	2024-08-21	8.8	High
		Insufficient data validation in V8 API in Google Chrome prior to			
		128.0.6613.84 allowed a remote attacker to potentially exploit			
CVE 2024 7074	Casala	heap corruption via a crafted Chrome Extension. (Chromium	2024 00 24	0.0	118.4
CVE-2024-7974	Google	security severity: Medium)  Dell Power Manager (DPM), versions 3.15.0 and prior, contains an	2024-08-21	8.8	High
		Incorrect Privilege Assignment vulnerability. A low privileged			
		attacker with local access could potentially exploit this			
		vulnerability, leading to Code execution and Elevation of			
CVE-2024-39576	Dell	privileges.	2024-08-22	8.8	High
		Zohocorp ManageEngine ADAudit Plus versions below 8000 are			
CVE-2024-36514	ManageEngine	vulnerable to the authenticated SQL injection in file summary option.	2024-08-23	8.8	High
VE-2024-30314	Managerngine	Zohocorp ManageEngine ADAudit Plus versions below 8000 are	2024-06-23	0.0	півіі
		vulnerable to the authenticated SQL injection in dashboard.			
		Note: This vulnerability is different from another vulnerability			
		(CVE-2024-36516), both of which have affected ADAudit Plus'			
CVE-2024-36515	ManageEngine	dashboard.	2024-08-23	8.8	High
		Zohocorp ManageEngine ADAudit Plus versions below 8000 are vulnerable to the authenticated SQL injection in dashboard.			
		Note: This vulnerability is different from another vulnerability			
		(CVE-2024-36515), both of which have affected ADAudit Plus'			
CVE-2024-36516	ManageEngine	dashboard.	2024-08-23	8.8	High
CVE 2024 26547	N.A	Zohocorp ManageEngine ADAudit Plus versions below 8000 are	2024 00 22	0.0	112.1
CVE-2024-36517	ManageEngine	vulnerable to the authenticated SQL injection in alerts module.  Zohocorp ManageEngine OpManager and Remote Monitoring and	2024-08-23	8.8	High
		Management versions 128329 and below are vulnerable to the			
CVE-2024-5466	ManageEngine	authenticated remote code execution in the deploy agent option.	2024-08-23	8.8	High
		Zohocorp ManageEngine ADAudit Plus versions below 8121 are			
		vulnerable to the authenticated SQL injection in account lockout			
CVE-2024-5467	ManageEngine	report.	2024-08-23	8.8	High
		Zohocorp ManageEngine ADAudit Plus versions below 8000 are vulnerable to the authenticated SQL injection in aggregate reports			
CVE-2024-5490	ManageEngine	option.	2024-08-23	8.8	High
<u> </u>		Zohocorp ManageEngine ADAudit Plus versions below 8000 are	3-10020		
CVE-2024-5556	ManageEngine	vulnerable to the authenticated SQL injection in reports module.	2024-08-23	8.8	High
		Zohocorp ManageEngine ADAudit Plus versions below 8121 are			
CVE 2024 FF00	Managa F : - :	vulnerable to the authenticated SQL injection in extranet lockouts	2024 00 22	0.0	118.1
CVE-2024-5586	ManageEngine	report option.  A vulnerability in the SIP call processing function of Cisco Unified	2024-08-23	8.8	High
		Communications Manager (Unified CM) and Cisco Unified			
		Communications Manager Session Management Edition (Unified			
		CM SME) could allow an unauthenticated, remote attacker to			
		cause a denial of service (DoS) condition on an affected device.			
		This vulnerability is due to improper parsing of SIP messages. An			
		attacker could exploit this vulnerability by sending a crafted SIP			
		message to an affected Cisco Unified CM or Cisco Unified CM SME			
		device. A successful exploit could allow the attacker to cause the			
		device to reload, resulting in a DoS condition that interrupts the			
CVE-2024-20375	Cisco	communications of reliant voice and video devices.	2024-08-21	8.6	High
		IBM App Connect Enterprise Certified Container 5.0, 7.1, 7.2, 8.0, 8.1, 8.2, 9.0, 9.1, 9.2, 10.0, 10.1, 11.0, 11.1, 11.2, 11.3, 11.4, 11.5,			
· ·					

		This can allow a user with access to execute commands in a			
		running Pod to elevate their user privileges.			
		In sendDeviceState_1_6 of RadioExt.cpp, there is a possible use after free due to improper locking. This could lead to local			
		escalation of privilege with no additional execution privileges			
CVE-2024-32927	Google	needed. User interaction is not needed for exploitation.  In the Linux kernel, the following vulnerability has been resolved:	2024-08-19	7.8	High
		misc: fastrpc: Fix use-after-free and race in fastrpc_map_find			
		Currently, there is a race window between the point when the			
		mutex is unlocked in fastrpc_map_lookup and the reference count			
		increasing (fastrpc_map_find, which can also lead to			
		use-after-free.			
		So lets merge fastrpc_map_find into fastrpc_map_lookup which			
		allows us			
		to both protect the maps list by also taking the &fl->lock spinlock and			
CVE-2022-48874	Linux	the reference count, since the spinlock will be released only after.  Add take_ref argument to make this suitable for all callers.	2024-08-21	7.8	High
<u>CVL-2022-48874</u>	Liliux	In the Linux kernel, the following vulnerability has been resolved:	2024-08-21	7.0	Tilgii
		Bluetooth: hci_qca: Fix driver shutdown on closed serdev			
		The driver shutdown callback (which sends EDL_SOC_RESET to the device			
		over serdev) should not be invoked when HCl device is not open			
		(e.g. if hci_dev_open_sync() failed), because the serdev and its TTY are			
		not open either. Also skip this step if device is powered off			
		(qca_power_shutdown()).			
		The shutdown callback causes use-after-free during system reboot			
		with			
		Qualcomm Atheros Bluetooth:			
		Unable to handle kernel paging request at virtual address 0072662f67726fd7			
		CPU: 6 PID: 1 Comm: systemd-shutdow Tainted: G W			
		6.1.0-rt5-00325-g8a5f56bcfcca #8  Hardware name: Qualcomm Technologies, Inc. Robotics RB5 (DT)			
		Call trace:			
		tty_driver_flush_buffer+0x4/0x30 serdev_device_write_flush+0x24/0x34			
		qca_serdev_shutdown+0x80/0x130 [hci_uart]			
		device_shutdown+0x15c/0x260 kernel_restart+0x48/0xac			
		KASAN report:			
		BUG: KASAN: use-after-free in tty_driver_flush_buffer+0x1c/0x50			
		Read of size 8 at addr ffff16270c2e0018 by task systemd-shutdow/1			
		CPU: 7 PID: 1 Comm: systemd-shutdow Not tainted 6.1.0-next-20221220-00014-gb85aaf97fb01-dirty #28			
		Hardware name: Qualcomm Technologies, Inc. Robotics RB5 (DT) Call trace:			
		dump_backtrace.part.0+0xdc/0xf0			
		show_stack+0x18/0x30 dump_stack_lvl+0x68/0x84			
		print_report+0x188/0x488			
		kasan_report+0xa4/0xf0 asan load8+0x80/0xac			
		tty_driver_flush_buffer+0x1c/0x50			
		ttyport_write_flush+0x34/0x44 serdev_device_write_flush+0x48/0x60			
		qca_serdev_shutdown+0x124/0x274			
		device_shutdown+0x1e8/0x350 kernel_restart+0x48/0xb0			
		do_sys_reboot+0x244/0x2d0			
		arm64_sys_reboot+0x54/0x70 invoke_syscall+0x60/0x190			
CVE-2022-48878	Linux	el0_svc_common.constprop.0+0x7c/0x160 do_el0_svc+0x44/0xf0	2024-08-21	7.8	High
CVL 2022-400/0	LIIIUA	40_610_376.0777/0/10	202 <del>4</del> -00-21	7.0	ı ıığıı

		el0_svc+0x2c/0x6c			
		el0_svc+0x2c/0x6c el0t_64_sync_handler+0xbc/0x140			
		el0t_64_sync+0x190/0x194			
		In the Linux kernel, the following vulnerability has been resolved:			
		sched/core: Fix use-after-free bug in dup_user_cpus_ptr()			
		Since commit 07ec77a1d4e8 ("sched: Allow task CPU affinity to be			
		restricted on asymmetric systems"), the setting and clearing of			
		user_cpus_ptr are done under pi_lock for arm64 architecture.  However,			
		dup_user_cpus_ptr() accesses user_cpus_ptr without any lock			
		protection. Since sched_setaffinity() can be invoked from another			
		process, the process being modified may be undergoing fork() at			
		the same time. When racing with the clearing of user_cpus_ptr inset_cpus_allowed_ptr_locked(), it can lead to user-after-free			
		and possibly double-free in arm64 kernel.			
		Commit 8f9ea86fdf99 ("sched: Always preserve the user			
		requested			
		cpumask") fixes this problem as user_cpus_ptr, once set, will			
		never be cleared in a task's lifetime. However, this bug was re-			
		introduced			
		in commit 851a723e45d1 ("sched: Always clear user_cpus_ptr in			
		do_set_cpus_allowed()") which allows the clearing of user_cpus_ptr in			
		do_set_cpus_allowed(). This time, it will affect all arches.			
		Final has been been been been been been been bee			
		Fix this bug by always clearing the user_cpus_ptr of the newly cloned/forked task before the copying process starts and check			
		the			
		user_cpus_ptr state of the source task under pi_lock.			
		Note to stable, this patch won't be applicable to stable releases.			
CVE-2022-48892	Linux	Just copy the new dup_user_cpus_ptr() function over.	2024-08-21	7.8	High
		Dell Repository Manager version 3.4.2 and earlier, contain a Local Privilege Escalation Vulnerability in Installation module. A local low			
		privileged attacker may potentially exploit this vulnerability			
		leading to the execution of arbitrary executable on the operating			
		system with high privileges using the existing vulnerability in			
CVE-2023-22576	Dell	operating system. Exploitation may lead to unavailability of the service.	2024-08-21	7.8	High
		Insufficient data validation in Installer in Google Chrome on			U
		Windows prior to 128.0.6613.84 allowed a local attacker to			
CVE-2024-7977	Google	perform privilege escalation via a malicious file. (Chromium security severity: Medium)	2024-08-21	7.8	High
	0	Insufficient data validation in Installer in Google Chrome on		-	<u> </u>
		Windows prior to 128.0.6613.84 allowed a local attacker to			
CVE-2024-7979	Google	perform privilege escalation via a crafted symbolic link. (Chromium security severity: Medium)	2024-08-21	7.8	High
312 202 1 1 3 1 3	0008.0	Insufficient data validation in Installer in Google Chrome on		7.0	6
		Windows prior to 128.0.6613.84 allowed a local attacker to			
CVE-2024-7980	Google	perform privilege escalation via a crafted symbolic link. (Chromium security severity: Medium)	2024-08-21	7.8	High
<u> </u>	3338.5	In the Linux kernel, the following vulnerability has been resolved:		7.0	
		netfilter: fix use-after-free innf_register_net_hook()			
		We must not develorence Green health of the state of			
		We must not dereference @new_hooks after nf_hook_mutex has been released,			
		because other threads might have freed our allocated hooks			
		already.			
		BUG: KASAN: use-after-free in nf_hook_entries_get_hook_ops			
		include/linux/netfilter.h:130 [inline]			
		BUG: KASAN: use-after-free in hooks_validate net/netfilter/core.c:171 [inline]			
		BUG: KASAN: use-after-free in			
		nf_register_net_hook+0x77a/0x820 net/netfilter/core.c:438			
		Read of size 2 at addr ffff88801c1a8000 by task syzexecutor237/4430			
		CACCULO1237/7730			
		CPU: 1 PID: 4430 Comm: syz-executor237 Not tainted 5.17.0-rc5-			
		syzkaller-00306-g2293be58d6a1 #0 Hardware name: Google Google Compute Engine/Google Compute			
		Engine, BIOS Google 01/01/2011			
0.45		Call Trace:			
CVE-2022-48912	Linux	<task></task>	2024-08-22	7.8	High

T			1	
	dump_stack lib/dump_stack.c:88 [inline] dump_stack_lvl+0xcd/0x134 lib/dump_stack.c:106			
	print_address_description.constprop.0.cold+0x8d/0x336 mm/kasan/report.c:255			
	kasan_report mm/kasan/report.c:442 [inline]			
	kasan_report.cold+0x83/0xdf mm/kasan/report.c:459 nf_hook_entries_get_hook_ops include/linux/netfilter.h:130			
	[inline]			
	hooks_validate net/netfilter/core.c:171 [inline]nf_register_net_hook+0x77a/0x820 net/netfilter/core.c:438			
	nf_register_net_hook+0x114/0x170 net/netfilter/core.c:571			
	nf_register_net_hooks+0x59/0xc0 net/netfilter/core.c:587			
	nf_synproxy_ipv6_init+0x85/0xe0 net/netfilter/nf_synproxy_core.c:1218			
	synproxy_tg6_check+0x30d/0x560			
	net/ipv6/netfilter/ip6t_SYNPROXY.c:81 xt_check_target+0x26c/0x9e0 net/netfilter/x_tables.c:1038			
	check_target net/ipv6/netfilter/ip6_tables.c:530 [inline]			
	find_check_entry.constprop.0+0x7f1/0x9e0			
	net/ipv6/netfilter/ip6_tables.c:573 translate_table+0xc8b/0x1750 net/ipv6/netfilter/ip6_tables.c:735			
	do_replace net/ipv6/netfilter/ip6_tables.c:1153 [inline]			
	do_ip6t_set_ctl+0x56e/0xb90			
	net/ipv6/netfilter/ip6_tables.c:1639 nf_setsockopt+0x83/0xe0 net/netfilter/nf_sockopt.c:101			
	ipv6_setsockopt+0x122/0x180 net/ipv6/ipv6_sockglue.c:1024			
	rawv6_setsockopt+0xd3/0x6a0 net/ipv6/raw.c:1084			
	sys_setsockopt+0x2db/0x610 net/socket.c:2180do_sys_setsockopt net/socket.c:2191 [inline]			
	se_sys_setsockopt net/socket.c:2188 [inline]			
	x64_sys_setsockopt+0xba/0x150 net/socket.c:2188			
	do_syscall_x64 arch/x86/entry/common.c:50 [inline] do_syscall_64+0x35/0xb0 arch/x86/entry/common.c:80			
	entry_SYSCALL_64_after_hwframe+0x44/0xae			
	RIP: 0033:0x7f65a1ace7d9 Code: 28 00 00 00 75 05 48 83 c4 28 c3 e8 71 15 00 00 90 48 89 f8			
	48 89 f7 48 89 d6 48 89 ca 4d 89 c2 4d 89 c8 4c 8b 4c 24 08 0f 05			
	<48> 3d 01 f0 ff ff 73 01 c3 48 c7 c1 b8 ff ff ff 7d 8 64 89 01 48			
	RSP: 002b:00007f65a1a7f308 EFLAGS: 00000246 ORIG_RAX: 0000000000000036			
	RAX: ffffffffffda RBX: 0000000000000 RCX:			
	00007f65a1ace7d9			
	RDX: 000000000000040 RSI: 000000000000029 RDI: 0000000000000003			
	RBP: 00007f65a1b574c8 R08: 00000000000001 R09:			
	00000000000000			
	R10: 0000000020000000 R11: 000000000000246 R12: 00007f65a1b55130			
	R13: 00007f65a1b574c0 R14: 00007f65a1b24090 R15:			
	000000000022000			
	The buggy address belongs to the page:			
	page:ffffea0000706a00 refcount:0 mapcount:0 mapping:0000000000000000 index:0x0 pfn:0x1c1a8			
	flags: 0xfff000000000000(node=0 zone=1 lastcpupid=0x7ff)			
	raw: 00fff0000000000 ffffea0001c1b108 ffffea000046dd08			
	00000000000000000000000000000000000000			
	000000000000000000000000000000000000000			
	page dumped because: kasan: bad access detected			
	page_owner tracks the page as freed page last allocated via order 2, migratetype Unmovable, gfp_mask			
	0x52dc0(GFP_KERNEL GFP_NOWARN GFP_NORETRY GFP			
	_COMP GFP_ZERO), pid 4430, ts 1061781545818, free_ts			
	1061791488993 prep_new_page_mm/page_alloc.c:2434 [inline]			
	get_page_from_freelist+0xa72/0x2f50 mm/page_alloc.c:4165			
	alloc_pages+0x1b2/0x500 mm/page_alloc.c:5389			
	alloc_pages_node include/linux/gfp.h:572 [inline] alloc_pages_node include/linux/gfp.h:595 [inline]			
	kmalloc_large_node+0x62/0x130 mm/slub.c:4438			
	kmalloc_node+0x35a/0x4a0 mm/slub.			
	In the Linux kernel, the following vulnerability has been resolved:			
	blktrace: fix use after free for struct blk_trace			
CVE 2022 40042	When tracing the whole disk, 'dropped' and 'msg' will be created	2024 00 00	7.0	115.1
<u>CVE-2022-48913</u> Linux	under 'q->debugfs_dir' and 'bt->dir' is NULL, thus blk_trace_free()	2024-08-22	7.8	High

won't remove those files. What's worse, the following UAF can be triggered because of accessing stale 'dropped' and 'msg': ========= BUG: KASAN: use-after-free in blk\_dropped\_read+0x89/0x100 Read of size 4 at addr ffff88816912f3d8 by task blktrace/1188 CPU: 27 PID: 1188 Comm: blktrace Not tainted 5.17.0-rc4-next-20220217+ #469 Hardware name: QEMU Standard PC (i440FX + PIIX, 1996), BIOS ?-20190727\_073836-4 Call Trace: <TASK> dump\_stack\_lvl+0x34/0x44 print\_address\_description.constprop.0.cold+0xab/0x381 ? blk\_dropped\_read+0x89/0x100 ? blk\_dropped\_read+0x89/0x100 kasan\_report.cold+0x83/0xdf ? blk\_dropped\_read+0x89/0x100 kasan\_check\_range+0x140/0x1b0 blk\_dropped\_read+0x89/0x100 ? blk create buf file callback+0x20/0x20 ? kmem\_cache\_free+0xa1/0x500 ? do sys openat2+0x258/0x460 full\_proxy\_read+0x8f/0xc0 vfs\_read+0xc6/0x260 ksys\_read+0xb9/0x150 ? vfs\_write+0x3d0/0x3d0 ? fpregs\_assert\_state\_consistent+0x55/0x60 ? exit\_to\_user\_mode\_prepare+0x39/0x1e0 do\_syscall\_64+0x35/0x80 entry\_SYSCALL\_64\_after\_hwframe+0x44/0xae RIP: 0033:0x7fbc080d92fd Code: ce 20 00 00 75 10 b8 00 00 00 00 0f 05 48 3d 01 f0 ff ff 73 31 c3 48 83 1 RSP: 002b:00007fbb95ff9cb0 EFLAGS: 00000293 ORIG\_RAX: 0000000000000000 RAX: ffffffffffda RBX: 00007fbb95ff9dc0 RCX: 00007fbc080d92fd RDX: 000000000000100 RSI: 00007fbb95ff9cc0 RDI: 000000000000045 RBP: 000000000000045 R08: 000000000406299 R09: 0000000ffffffd R10: 00000000153afa0 R11: 000000000000293 R12: 00007fbb780008c0 R13: 00007fbb78000938 R14: 0000000000608b30 R15: 00007fbb780029c8 </TASK> Allocated by task 1050: kasan\_save\_stack+0x1e/0x40 \_kasan\_kmalloc+0x81/0xa0 do blk trace setup+0xcb/0x410 blk trace setup+0xac/0x130 blk\_trace\_ioctl+0xe9/0x1c0 blkdev\_ioctl+0xf1/0x390 \_x64\_sys\_ioctl+0xa5/0xe0 do syscall 64+0x35/0x80 entry\_SYSCALL\_64\_after\_hwframe+0x44/0xae Freed by task 1050: kasan\_save\_stack+0x1e/0x40 kasan\_set\_track+0x21/0x30 kasan\_set\_free\_info+0x20/0x30 \_kasan\_slab\_free+0x103/0x180 kfree+0x9a/0x4c0 \_blk\_trace\_remove+0x53/0x70 blk\_trace\_ioctl+0x199/0x1c0 blkdev\_common\_ioctl+0x5e9/0xb30 blkdev\_ioctl+0x1a5/0x390 \_x64\_sys\_ioctl+0xa5/0xe0 do\_syscall\_64+0x35/0x80 entry\_SYSCALL\_64\_after\_hwframe+0x44/0xae The buggy address belongs to the object at ffff88816912f380 which belongs to the cache kmalloc-96 of size 96 The buggy address is located 88 bytes inside of 96-byte region [ffff88816912f380, ffff88816912f3e0) The buggy address belongs to the page: page:000000009a1b4e7c refcount:1 mapcount:0

		mapping:000000000000000000000 index:0x0f			
		flags: 0x17ffffc0000200(slab node=0 zone=2 lastcpupid=0x1fffff)			
		raw: 0017ffffc0000200 ffffea00044f1100 dead0000000000002			
		ffff88810004c780			
		raw: 000000000000000 0000000000200020 000000			
		00000000000000			
		page dumped because: kasan: bad access detected			
		Memory state around the buggy address:			
		ffff88816912f280: fa fb fb fb fb fb fb fb fb fb fc fc fc fc			
		ffff88816912f300: fa fb fc fc fc			
		>ffff88816912f380: fa fb fb fb fb fb fb fb fb fb fc fc fc fc			
		V. V			
		ffff88816912f400: fa fb fb fb fb fb fb fb fb fb fc fc fc fc			
		ffff88816912f480: fa fb fb fb fb fb fb fb fb fb fc fc fc fc			
		=======================================			
		========			
		In the Linux kernel, the following vulnerability has been resolved:			
		cifs: fix double free race when mount fails in cifs get root()			
		When cifs_get_root() fails during cifs_smb3_do_mount() we call			
		deactivate_locked_super() which eventually will call			
		delayed_free() which			
		will free the context.			
		In this situation we should not proceed to enter the out: section in			
		cifs_smb3_do_mount() and free the same resources a second			
		time.			
		[Thu Feb 10 12:59:06 2022] BUG: KASAN: use-after-free in			
		rcu_cblist_dequeue+0x32/0x60			
		[Thu Feb 10 12:59:06 2022] Read of size 8 at addr			
		ffff888364f4d110 by task swapper/1/0			
		тине в при			
		[Thu Feb 10 12:59:06 2022] CPU: 1 PID: 0 Comm: swapper/1			
		Tainted: G OE 5.17.0-rc3+ #4			
		[Thu Feb 10 12:59:06 2022] Hardware name: Microsoft			
		Corporation Virtual Machine/Virtual Machine, BIOS Hyper-V UEFI			
		Release v4.0 12/17/2019			
		[Thu Feb 10 12:59:06 2022] Call Trace:			
		[Thu Feb 10 12:59:06 2022] <irq></irq>			
		[Thu Feb 10 12:59:06 2022] dump_stack_lvl+0x5d/0x78			
		[Thu Feb 10 12:59:06 2022]			
		print_address_description.constprop.0+0x24/0x150			
		[Thu Feb 10 12:59:06 2022] ? rcu_cblist_dequeue+0x32/0x60			
		[Thu Feb 10 12:59:06 2022] kasan_report.cold+0x7d/0x117			
		[Thu Feb 10 12:59:06 2022] Rasan_Teport:cold+0x7d/0x117			
		[Thu Feb 10 12:59:06 2022]asan_load8+0x86/0xa0			
		[Thu Feb 10 12:59:06 2022] rcu_cblist_dequeue+0x32/0x60			
		[Thu Feb 10 12:59:06 2022] rcu_core+0x547/0xca0			
		[Thu Feb 10 12:59:06 2022] ? call_rcu+0x3c0/0x3c0			
		[Thu Feb 10 12:59:06 2022] ?			
		this_cpu_preempt_check+0x13/0x20			
		[Thu Feb 10 12:59:06 2022] ? lock_is_held_type+0xea/0x140			
		[Thu Feb 10 12:59:06 2022] rcu_core_si+0xe/0x10			
		[Thu Feb 10 12:59:06 2022]do_softirq+0x1d4/0x67b			
		[Thu Feb 10 12:59:06 2022]irq_exit_rcu+0x100/0x150			
		[Thu Feb 10 12:59:06 2022]iiq_exit_rcu+0x100/0x130			
		[Thu Feb 10 12:59:06 2022] Ird_exit_rcu+0xe/0x30 [Thu Feb 10 12:59:06 2022] sysvec hyperv stimer0+0x9d/0xc0			
		[ [ [ [ [ ] ] ] ] [ [ ] ] [ ] [ ] [ ] [			
		[Thu Feb 40 42 F0 07 2022] 5			
		[Thu Feb 10 12:59:07 2022] Freed by task 58179:			
		[Thu Feb 10 12:59:07 2022] kasan_save_stack+0x26/0x50			
		[Thu Feb 10 12:59:07 2022] kasan_set_track+0x25/0x30			
		[Thu Feb 10 12:59:07 2022] kasan_set_free_info+0x24/0x40			
		[Thu Feb 10 12:59:07 2022]kasan_slab_free+0x137/0x170			
		[Thu Feb 10 12:59:07 2022]kasan_slab_free+0x12/0x20			
		[Thu Feb 10 12:59:07 2022] slab free freelist hook+0xb3/0x1d0			
		[Thu Feb 10 12:59:07 2022] kfree+0xcd/0x520			
		[Thu Feb 10 12:59:07 2022] kinee+0xcd/0x320			
		[ [Titu Feb 10 12.59.07 2022]			
		[Thu Feb 10 12:59:07 2022] smb3_get_tree+0x1a0/0x2e0 [cifs]			
		[Thu Feb 10 12:59:07 2022] vfs_get_tree+0x52/0x140			
		[Thu Feb 10 12:59:07 2022] path_mount+0x635/0x10c0			
		[Thu Feb 10 12:59:07 2022]x64_sys_mount+0x1bf/0x210			
		[Thu Feb 10 12:59:07 2022] do_syscall_64+0x5c/0xc0			
		[Thu Feb 10 12:59:07 2022]			
		entry_SYSCALL_64_after_hwframe+0x44/0xae			
		[Thu Feb 10 12:59:07 2022] Last potentially related work creation:			
	Ī		İ		l
CVE-2022-48919	Linux	[Thu Feb 10 12:59:07 2022] kasan save stack+0x26/0x50	2024-08-22	7.8	High

			[Thu Feb 10 12:59:07 2022]			
			kasan_record_aux_stack+0xb6/0xc0			
			[Thu Feb 10 12:59:07 2022]			
			kasan_record_aux_stack_noalloc+0xb/0x10			
			[Thu Feb 10 12:59:07 2022] call_rcu+0x76/0x3c0			
			[Thu Feb 10 12:59:07 2022] cifs_umount+0xce/0xe0 [cifs]			
			[Thu Feb 10 12:59:07 2022] cifs_kill_sb+0xc8/0xe0 [cifs]			
			[Thu Feb 10 12:59:07 2022] deactivate_locked_super+0x5d/0xd0			
			[Thu Feb 10 12:59:07 2022] cifs_smb3_do_mount+0xab9/0xbe0 [cifs]			
			[Thu Feb 10 12:59:07 2022] smb3_get_tree+0x1a0/0x2e0 [cifs] [Thu Feb 10 12:59:07 2022] vfs_get_tree+0x52/0x140			
			[Thu Feb 10 12:59:07 2022] vis_get_tree+0x32/0x140			
			· · · -			
			[Thu Feb 10 12:59:07 2022]x64_sys_mount+0x1bf/0x210 [Thu Feb 10 12:59:07 2022] do syscall 64+0x5c/0xc0			
			[Thu Feb 10 12:59:07 2022] ub_systail_04+0x3t/0xt0			
			entry_SYSCALL_64_after_hwframe+0x44/0xae			
			In the Linux kernel, the following vulnerability has been resolved:			
			in the Linux Kerner, the following vulnerability has been resolved.			
			RDMA/cma: Do not change route.addr.src addr outside state			
			checks			
			Checks			
			If the state is not idle then resolve_prepare_src() should			
			immediately			
			fail and no change to global state should happen. However, it			
			unconditionally overwrites the src_addr trying to build a			
			temporary any			
			address.			
			uuui C33.			
			For instance if the state is already RDMA_CM_LISTEN then this will			
			corrupt			
			the src_addr and would cause the test in cma_cancel_operation():			
			the sto_addrana would eduse the test in tina_cancei_operation().			
			if (cma_any_addr(cma_src_addr(id_priv)) && !id_priv-			
			>cma_dev)			
			<u>-</u>			
			Which would manifest as this trace from syzkaller:			
			·			
			BUG: KASAN: use-after-free inlist_add_valid+0x93/0xa0			
			lib/list_debug.c:26			
			Read of size 8 at addr ffff8881546491e0 by task syz-			
			executor.1/32204			
			CPU: 1 PID: 32204 Comm: syz-executor.1 Not tainted 5.12.0-rc8-			
			syzkaller #0			
			Hardware name: Google Google Compute Engine/Google			
			Compute Engine, BIOS Google 01/01/2011			
			Call Trace:			
			dump_stack lib/dump_stack.c:79 [inline]			
			dump_stack+0x141/0x1d7 lib/dump_stack.c:120			
			print_address_description.constprop.0.cold+0x5b/0x2f8			
			mm/kasan/report.c:232			
			kasan_report mm/kasan/report.c:399 [inline]			
			kasan_report.cold+0x7c/0xd8 mm/kasan/report.c:416			
			list_add_valid+0x93/0xa0 lib/list_debug.c:26			
			list_add include/linux/list.h:67 [inline]			
			list_add_tail include/linux/list.h:100 [inline]			
			cma_listen_on_all drivers/infiniband/core/cma.c:2557 [inline]			
			rdma_listen+0x787/0xe00 drivers/infiniband/core/cma.c:3751			
			ucma listen+0x16a/0x210 drivers/infiniband/core/ucma.c:1102			
			ucma write+0x259/0x350 drivers/infiniband/core/ucma.c:1732			
			vfs write+0x28e/0xa30 fs/read write.c:603			
			ksys write+0x1ee/0x250 fs/read write.c:658			
			do_syscall_64+0x2d/0x70 arch/x86/entry/common.c:46			
			entry_SYSCALL_64_after_hwframe+0x44/0xae			
			, ,			
			This is indicating that an rdma_id_private was destroyed without			
			doing			
			cma_cancel_listens().			
			Instead of trying to re-use the src_addr memory to indirectly			
			create an			
			any address derived from the dst build one explicitly on the stack			
			and			
			bind to that as any other normal flow would do. rdma_bind_addr()			
			will copy			
			it over the src_addr once it knows the state is valid.			
CVF-201	22-48925	Linux	This is similar to commit bc0bdc5afaa7 ("RDMA/cma: Do not	2024-08-22	7.8	High
UV L-2U	LL +UJLJ	LIIIUX	This is similar to commit beobacsaraa? ( NDIVIA/CITIA, DO HOL	2024-00-22	7.0	ıııgıı

		change			<u> </u>
		route.addr.src_addr.ss_family")			
		In the Linux kernel, the following vulnerability has been resolved:			
		usb: gadget: rndis: add spinlock for rndis response list			
		There's no lock for rndis response list. It could cause list corruption if there're two different list_add at the same time like below. It's better to add in rndis_add_response / rndis_free_response / rndis_get_next_response to prevent any race condition on response list.			
		[ 361.894299] [1: irq/191-dwc3:16979] list_add corruption. next->prev should be prev (fffff80651764d0), but was ffffff883dc36f80. (next=fffff80651764d0).			
CVE-2022-48926	Linux	[ 361.904380] [1: irq/191-dwc3:16979] Call trace: [ 361.904391] [1: irq/191-dwc3:16979]   list_add_valid+0x74/0x90 [ 361.904401] [1: irq/191-dwc3:16979]    rndis_msg_parser+0x168/0x8c0 [ 361.904409] [1: irq/191-dwc3:16979]    rndis_command_complete+0x24/0x84 [ 361.904417] [1: irq/191-dwc3:16979]    usb_gadget_giveback_request+0x20/0xe4 [ 361.904426] [1: irq/191-dwc3:16979]    dwc3_gadget_giveback+0x44/0x60 [ 361.904434] [1: irq/191-dwc3:16979]    dwc3_ep0_complete_data+0x1e8/0x3a0 [ 361.904442] [1: irq/191-dwc3:16979]    dwc3_ep0_interrupt+0x29c/0x3dc [ 361.904450] [1: irq/191-dwc3:16979]    dwc3_process_event_entry+0x78/0x6cc [ 361.904457] [1: irq/191-dwc3:16979]    dwc3_process_event_buf+0xa0/0x1ec [ 361.904465] [1: irq/191-dwc3:16979]    dwc3_thread_interrupt+0x34/0x5c  In the Linux kernel, the following vulnerability has been resolved:  iio: adc: tsc2046: fix memory corruption by preventing array overflow	2024-08-22	7.8	High
		On one side we have indio_dev->num_channels includes all physical channels + timestamp channel. On other side we have an array allocated only for physical channels. So, fix memory corruption by ARRAY_SIZE() instead of num_channels variable.			
		Note the first case is a cleanup rather than a fix as the software timestamp channel bit in active_scanmask is never set by the IIO			
CVE-2022-48927	Linux	core.	2024-08-22	7.8	High
		In the Linux kernel, the following vulnerability has been resolved:			
		KVM: x86/mmu: make apf token non-zero to fix bug			
		In current async pagefault logic, when a page is ready, KVM relies on			
		kvm_arch_can_dequeue_async_page_present() to determine whether to deliver			
		a READY event to the Guest. This function test token value of struct			
		kvm_vcpu_pv_apf_data, which must be reset to zero by Guest kernel when a			
		READY event is finished by Guest. If value is zero meaning that a READY			
		event is done, so the KVM can deliver another.  But the kvm_arch_setup_async_pf() may produce a valid token with zero			
		value, which is confused with previous mention and may lead the loss of			
		this READY event.			
		This bug may cause task blocked forever in Guest: INFO: task stress:7532 blocked for more than 1254 seconds. Not tainted 5.10.0 #16			
		"echo 0 > /proc/sys/kernel/hung_task_timeout_secs" disables this message.			
CVE-2022-48943	Linux	task:stress state:D stack: 0 pid: 7532 ppid: 1409	2024-08-22	7.8	High

		flags:0x00000080			_
		Call Trace: schedule+0x1e7/0x650			
		schedule+0x46/0xb0		1	
		kvm_async_pf_task_wait_schedule+0xad/0xe0		1	
		? exit_to_user_mode_prepare+0x60/0x70		n	
		kvm_handle_async_pf+0x4f/0xb0 ? asm_exc_page_fault+0x8/0x30		n	
		exc_page_fault+0x6f/0x110		n	
		? asm_exc_page_fault+0x8/0x30		n	
		asm_exc_page_fault+0x1e/0x30		n	
		RIP: 0033:0x402d00 RSP: 002b:00007ffd31912500 EFLAGS: 00010206		n	
		RAX: 000000000071000 RBX: ffffffffffff RCX:		n	
		0000000021a32b0		n	
		RDX: 00000000007d011 RSI: 00000000007d000 RDI:		n	
		0000000021262b0 RBP: 0000000021262b0 R08: 00000000000000 R09:		n	
		0000000000000086		n	
		R10: 00000000000000eb R11: 00007fefbdf2baa0 R12:		n	
		00000000000000		n	
		R13: 0000000000000002 R14: 00000000007d000 R15:		n	
		000000000001000  Microsoft Edge (Chromium-based) Remote Code Execution			
CVE-2024-38209	Microsoft	Vulnerability	2024-08-22	7.8	High
		Microsoft Edge (Chromium-based) Remote Code Execution			
CVE-2024-38210	Microsoft	Vulnerability	2024-08-22	7.8	High
		This High severity RCE (Remote Code Execution) vulnerability CVE-		n	
		2024-21689 was introduced in versions 9.1.0, 9.2.0, 9.3.0, 9.4.0, 9.5.0, and 9.6.0 of Bamboo Data Center and Server.	 	in and the second	
		5.5.5, and 5.6.5 or barrisoo bata center and server.	 	in and the second	
		This DCE (Domete Code Everyties) and some billion with a CLICS C			
		This RCE (Remote Code Execution) vulnerability, with a CVSS Score of 7.6, allows an authenticated attacker to execute arbitrary code			
		which has high impact to confidentiality, high impact to integrity,			
		high impact to availability, and requires user interaction.		n	
				n	
				n	
		Atlassian recommends that Bamboo Data Center and Server		n	
		customers upgrade to latest version, if you are unable to do so,		n	
		upgrade your instance to one of the specified supported fixed		n	
		versions:		n	
		Bamboo Data Center and Server 9.2: Upgrade to a release greater		n	
		than or equal to 9.2.17		n	
				n	
				n	
		Bamboo Data Center and Server 9.6: Upgrade to a release greater	 	in and the second	
		than or equal to 9.6.5			
		• • • • • • • • • • • • • • • • • • • •		n l	
		Soo the valence vistes	 		
		See the release notes ([https://confluence.atlassian.com/bambooreleases/bamboo-	 		
		release-notes-1189793869.html]). You can download the latest		n	
		version of Bamboo Data Center and Server from the download		n	
		center ([https://www.atlassian.com/software/bamboo/download-		n	
		archives]).			
				n l	
CVE-2024-21689	Atlassian	This vulnerability was reported via our Bug Bounty program.	2024-08-20	7.6	High
		IBM Sterling Connect:Direct Web Services 6.0, 6.1, 6.2, and 6.3			
CVE-2024-39745	IBM	uses weaker than expected cryptographic algorithms that could allow an attacker to decrypt highly sensitive information.	2024-08-22	7.5	⊔iah
CVE-2U24-39/45	IDIVI	Improper access control in Decentralized Identity Services allows	ZUZ4-Uŏ-ZZ	7.5	High
		an unathenticated attacker to disable Verifiable ID's on another	 		
CVE-2024-43477	Microsoft	tenant.	2024-08-23	7.5	High
		Dell SupportAssist for Home PCs Installer exe version 4.0.3			
		contains a privilege escalation vulnerability in the installer. A local			
		low-privileged authenticated attacker could potentially exploit this vulnerability, leading to the execution of arbitrary executables on	 		
CVE-2024-38305	Dell	the operating system with elevated privileges.	2024-08-21	7.3	High
		In the Linux kernel, the following vulnerability has been resolved:	-		<del></del>
				,	
			,	l	
CVE-2022-48881	Linux	platform/x86/amd: Fix refcount leak in amd_pmc_probe	2024-08-21	7.1	High

		pci_get_domain_bus_and_slot() takes reference, the caller should release			
		the reference by calling pci_dev_put() after use. Call pci_dev_put() in			
		the error path to fix this.  This High severity Reflected XSS and CSRF (Cross-Site Request			
		Forgery) vulnerability was introduced in versions 7.19.0, 7.20.0,			
		8.0.0, 8.1.0, 8.2.0, 8.3.0, 8.4.0, 8.5.0, 8.6.0, 8.7.1, 8.8.0, and 8.9.0			
		of Confluence Data Center and Server.			
		This Reflected XSS and CSRF (Cross-Site Request Forgery)			
		vulnerability, with a CVSS Score of 7.1, allows an unauthenticated attacker to execute arbitrary HTML or JavaScript code on a victims			
		browser and force a end user to execute unwanted actions on a			
		web application in which they're currently authenticated which			
		has high impact to confidentiality, low impact to integrity, no impact to availability, and requires user interaction.			
		Atlassian recommends that Confluence Data Center and Server			
		customers upgrade to latest version, if you are unable to do so,			
		upgrade your instance to one of the specified supported fixed versions:			
		* Confluence Data Center and Server 7.19: Upgrade to a release greater than or equal to 7.19.26			
		* Confluence Data Center and Server 8.5: Upgrade to a release greater than or equal to 8.5.14			
		* Confluence Data Center and Server 9.0: Upgrade to a release			
		greater than or equal to 9.0.1			
		See the release notes			
		(https://confluence.atlassian.com/doc/confluence-release-notes- 327.html). You can download the latest version of Confluence Data			
		Center and Server from the download center			
		(https://www.atlassian.com/software/confluence/download-archives).			
CVE-2024-21690	Atlassian	This vulnerability was reported via our Bug Bounty program.	2024-08-21	7.1	High
		NGINX Agent's "config_dirs" restriction feature allows a highly			
CVE-2024-7634	F5	privileged attacker to gain the ability to write/overwrite files outside of the designated secure directory.	2024-08-22	6.9	Medium
		IBM Global Configuration Management 7.0.2 and 7.0.3 could allow			
CVE-2024-41773	IBM	an authenticated user to archive a global baseline due to improper access controls.	2024-08-20	6.5	Medium
		Multiple vulnerabilities in the REST API of Cisco Identity Services Engine (ISE) could allow an authenticated, remote attacker to			
		conduct blind SQL injection attacks.			
		These vulnerabilities are due to insufficient validation of user- supplied input in REST API calls. An attacker could exploit these			
		vulnerabilities by sending crafted input to an affected device. A			
CVE 2024 20447	Ciara	successful exploit could allow the attacker to view or modify data	2024 00 24	6.5	NA - divers
<u>CVE-2024-20417</u>	Cisco	on the affected device.  A vulnerability in the web-based management interface of Cisco	2024-08-21	6.5	Medium
		Identity Services Engine (ISE) could allow an authenticated, remote			
		attacker to obtain sensitive information from an affected device.			
		This vulnerability is due to improper enforcement of			
		administrative privilege levels for high-value sensitive data. An attacker with read-only Administrator privileges for the web-based			
		management interface on an affected device could exploit this			
		vulnerability by browsing to a page that contains sensitive data. A successful exploit could allow the attacker to collect sensitive			
CVE-2024-20466	Cisco	information regarding the configuration of the system.	2024-08-21	6.5	Medium
		A vulnerability in the web-based management interface of Cisco Identity Services Engine (ISE) could allow an unauthenticated,			
		remote attacker to conduct a cross-site request forgery (CSRF) attack and perform arbitrary actions on an affected device.			
		accook and periorin arbitrary actions on an affected device.			
CVE-2024-20486	Cisco	This vulnerability is due to insufficient CSRF protections for the	2024-08-21	6.5	Medium

		web-based management interface of an affected device. An			
		attacker could exploit this vulnerability by persuading a user of the			
		interface to follow a crafted link. A successful exploit could allow			
		the attacker to perform arbitrary actions on the affected device with the privileges of the targeted user.			
		IBM OpenPages with Watson 8.3 and 9.0 could allow			
		authenticated users access to sensitive information through			
CVE-2024-35151	IBM	improper authorization controls on APIs.	2024-08-22	6.5	Medium
CVE-2024-38207	Microsoft	Microsoft Edge (HTML-based) Memory Corruption Vulnerability	2024-08-23	6.3	Medium
		A vulnerability in the web-based management interface of Cisco			
		Unified Communications Manager (Unified CM) and Cisco Unified			
		Communications Manager Session Management Edition (Unified			
		CM SME) could allow an unauthenticated, remote attacker to			
		conduct a cross-site scripting (XSS) attack against a user of the			
		interface.			
		This vulnerability exists because the web-based management			
		interface does not properly validate user-supplied input. An			
		attacker could exploit this vulnerability by persuading a user of the			
		interface to click a crafted link. A successful exploit could allow the			
		attacker to execute arbitrary script code in the context of the			
CVE-2024-20488	Cisco	affected interface or access sensitive, browser-based information.	2024-08-21	6.1	Medium
CVE-2024-38208	Microsoft	Microsoft Edge for Android Spoofing Vulnerability	2024-08-22	6.1	Medium
		An Stored Cross-site Scripting vulnerability in request module			
		affects Zohocorp ManageEngine ServiceDesk Plus, ServiceDesk			
		Plus MSP and SupportCenter Plus.This issue affects ServiceDesk			
CVE-2024-41150	ManageEngine	Plus versions: through 14810; ServiceDesk Plus MSP: through 14800; SupportCenter Plus: through 14800.	2024-08-23	6.1	Medium
CVL-2024-41130	ManageLiigilie	The libcurl CURLOPT SSL VERIFYPEER option was disabled on a	2024-08-23	0.1	Mediaiii
		subset of requests made by Nest production devices which			
		enabled a potential man-in-the-middle attack on requests to			
CVE-2024-32928	Google	Google cloud services by any host the traffic was routed through.	2024-08-19	5.9	Medium
		IBM Sterling Connect:Direct Web Services 6.0, 6.1, 6.2, and 6.3			
		could allow a remote attacker to obtain sensitive information,			
		caused by the failure to properly enable HTTP Strict Transport			
		Security. An attacker could exploit this vulnerability to obtain			
<u>CVE-2024-39746</u>	IBM	sensitive information using man in the middle techniques.	2024-08-22	5.9	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		wifi: mac80211: fix initialization of rx->link and rx->link sta			
		WIT: Mac80211: 11X Initialization of fx->link and fx->link_sta			
		There are some codepaths that do not initialize rx->link_sta			
		properly. This			
		causes a crash in places which assume that rx->link_sta is valid if			
		rx->sta			
		is valid.			
		One known instance is triggered byieee80211_rx_h_amsdu			
		being called from			
		fast-rx. It results in a crash like this one:			
		PLIC: karnal NULL paintar darafaranca address:			
		BUG: kernel NULL pointer dereference, address: 000000000000000a8			
		#PF: supervisor write access in kernel mode			
		#PF: error_code(0x0002) - not-present page PGD 0 P4D 0			
		Oops: 0002 [#1] PREEMPT SMP PTI			
		CPU: 1 PID: 506 Comm: mt76-usb-rx phy Tainted: G E			
		6.1.0-debian64x+1.7 #3			
		Hardware name: ZOTAC ZBOX-ID92/ZBOX-IQ01/ZBOX-ID92/ZBOX-			
		IQ01, BIOS B220P007 05/21/2014			
		RIP: 0010:ieee80211_deliver_skb+0x62/0x1f0 [mac80211]			
		Code: 00 48 89 04 24 e8 9e a7 c3 df 89 c0 48 03 1c c5 a0 ea 39 a1			
		4c 01 6b 08 48 ff 03 48 83 7d 28 00 74 11 48 8b 45 30 48 63 55 44 <48> 83 84 d0 a8 00			
		83 7d 28 00 74 11 48 8b 45 30 48 63 55 44 <48> 83 84 d0 a8 00 00 00 01 41 8b 86 c0			
		11 00 00 8d 50 fd 83 fa 01			
		RSP: 0018:ffff999040803b10 EFLAGS: 00010286			
		RAX: 00000000000000 RBX: ffffb9903f496480 RCX:			
		00000000000000			
		RDX: 000000000000000 RSI: 000000000000000 RDI:			
		00000000000000			
		RBP: ffff999040803ce0 R08: 00000000000000 R09:			
		00000000000000			
		R10: 000000000000000 R11: 00000000000000			
		ffff8d21828ac900			
		R13: 00000000000004a R14: ffff8d2198ed89c0 R15: ffff8d2198ed8000			
		FS: 0000000000000000(0000) GS:ffff8d24afe80000(0000)			
CVE-2022-48876	Linux	knlGS:000000000000000000000000000000000000	2024-08-21	5.5	Medium
				<del>-</del>	

				,	
		CS: 0010 DS: 0000 ES: 0000 CR0: 0000000080050033 CR2: 00000000000000a8 CR3: 0000000429810002 CR4:			
		000000001706e0 Call Trace:			
		<task></task>			
		ieee80211_rx_h_amsdu+0x1b5/0x240 [mac80211] ? ieee80211_prepare_and_rx_handle+0xcdd/0x1320 [mac80211]			
		?local_bh_enable_ip+0x3b/0xa0			
		ieee80211_prepare_and_rx_handle+0xcdd/0x1320 [mac80211] ? prepare_transfer+0x109/0x1a0 [xhci_hcd]			
		ieee80211_rx_list+0xa80/0xda0 [mac80211]			
		mt76_rx_complete+0x207/0x2e0 [mt76] mt76_rx_poll_complete+0x357/0x5a0 [mt76]			
		mt76u_rx_worker+0x4f5/0x600 [mt76_usb] ? mt76_get_min_avg_rssi+0x140/0x140 [mt76]			
		mt76_worker_fn+0x50/0x80 [mt76]			
		kthread+0xed/0x120 ? kthread_complete_and_exit+0x20/0x20			
		ret_from_fork+0x22/0x30			
		Since the initialization of rx->link and rx->link_sta is rather convoluted			
		and duplicated in many places, clean it up by using a helper			
		function to set it.			
		[remove unnecessary rx->sta->sta.mlo check] In the Linux kernel, the following vulnerability has been resolved:			
		efi: fix NULL-deref in init error path			
		·			
		In cases where runtime services are not supported or have been disabled,			
		the runtime services workqueue will never have been allocated.			
		Do not try to destroy the workqueue unconditionally in the			
		unlikely event that EFI initialisation fails to avoid dereferencing a NULL			
CVE-2022-48879	Linux	pointer.  In the Linux kernel, the following vulnerability has been resolved:	2024-08-21	5.5	Medium
		net/mlx5e: Fix macsec possible null dereference when updating MAC security entity (SecY)			
		Upon updating MAC security entity (SecY) in hw offload path, the macsec			
		security association (SA) initialization routine is called. In case of extended packet number (epn) is enabled the salt and ssci			
		attributes are			
		retrieved using the MACsec driver rx_sa context which is unavailable when			
		updating a SecY property such as encoding-sa hence the null			
CVE-2022-48882	Linux	dereference. Fix by using the provided SA to set those attributes.	2024-08-21	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		drm/msm/dpu: Fix memory leak in msm_mdss_parse_data_bus_icc_path			
		of_icc_get() alloc resources for path1, we should release it when			
		not need anymore. Early return when IS_ERR_OR_NULL(path0) may			
		leak path1.			
		Defer getting path1 to fix this.			
CVE-2022-48888	Linux	Patchwork: https://patchwork.freedesktop.org/patch/514264/ In the Linux kernel, the following vulnerability has been resolved:	2024-08-21	5.5	Medium
		thermal: core: Fix TZ_GET_TRIP NULL pointer dereference			
		Do not call get_trip_hyst() from thermal_genl_cmd_tz_get_trip() if			
CVE-2022-48915	Linux	the thermal zone does not define one.  In the Linux kernel, the following vulnerability has been resolved:	2024-08-22	5.5	Medium
		iwlwifi: mvm: check debugfs_dir ptr before use			
		When "debugfs=off" is used on the kernel command line, iwiwifi's			
		mvm module uses an invalid/unchecked debugfs_dir pointer and			
CVE-2022-48918	Linux	a BUG:	2024-08-22	5.5	Medium

```
BUG: kernel NULL pointer dereference, address:
00000000000004f
#PF: supervisor read access in kernel mode
#PF: error_code(0x0000) - not-present page
PGD 0 P4D 0
Oops: 0000 [#1] PREEMPT SMP
CPU: 1 PID: 503 Comm: modprobe Tainted: G
                                                   5.17.0-
rc5 #7
Hardware name: Dell Inc. Inspiron 15 5510/076F7Y, BIOS 2.4.1
11/05/2021
RIP: 0010:iwl_mvm_dbgfs_register+0x692/0x700 [iwlmvm]
Code: 69 a0 be 80 01 00 00 48 c7 c7 50 73 6a a0 e8 95 cf ee e0 48
8b 83 b0 1e 00 00 48 c7 c2 54 73 6a a0 be 64 00 00 00 48 8d 7d 8c
<48> 8b 48 50 e8 15 22 07 e1 48 8b 43 28 48 8d 55 8c 48 c7 c7 5f
73
RSP: 0018:ffffc90000a0ba68 EFLAGS: 00010246
RAX: ffffffffffff RBX: ffff88817d6e3328 RCX: ffff88817d6e3328
RDX: fffffffa06a7354 RSI: 0000000000000064 RDI:
ffffc90000a0ba6c
RBP: ffffc90000a0bae0 R08: fffffff824e4880 R09: fffffffa069d620
R13: ffffc90000a0bb28 R14: ffff88817d6e3328 R15:
ffff88817d6e3320
FS: 00007f64dd92d740(0000) GS:ffff88847f640000(0000)
CS: 0010 DS: 0000 ES: 0000 CR0: 0000000080050033
CR2: 000000000000004f CR3: 000000016fc79001 CR4:
000000000770ee0
PKRU: 5555554
Call Trace:
 <TASK>
 ? iwl_mvm_mac_setup_register+0xbdc/0xda0 [iwlmvm]
 iwl_mvm_start_post_nvm+0x71/0x100 [iwlmvm]
 iwl_op_mode_mvm_start+0xab8/0xb30 [iwlmvm]
 iwl op mode start+0x6f/0xd0 [iwlwifi]
 iwl opmode_register+0x6a/0xe0 [iwlwifi]
 ? 0xfffffffa0231000
 iwl_mvm_init+0x35/0x1000 [iwlmvm]
 ? 0xfffffffa0231000
 do_one_initcall+0x5a/0x1b0
 ? kmem_cache_alloc+0x1e5/0x2f0
 ? do_init_module+0x1e/0x220
 do init module+0x48/0x220
 load_module+0x2602/0x2bc0
 ? kernel read+0x145/0x2e0
 ? kernel_read_file+0x229/0x290
  _do_sys_finit_module+0xc5/0x130
 ? __do_sys_finit_module+0xc5/0x130
 __x64_sys_finit_module+0x13/0x20
 do_syscall_64+0x38/0x90
 entry_SYSCALL_64_after_hwframe+0x44/0xae
RIP: 0033:0x7f64dda564dd
Code: 5b 41 5c c3 66 0f 1f 84 00 00 00 00 00 f3 0f 1e fa 48 89 f8 48
89 f7 48 89 d6 48 89 ca 4d 89 c2 4d 89 c8 4c 8b 4c 24 08 0f 05
<48> 3d 01 f0 ff ff 73 01 c3 48 8b 0d 1b 29 0f 00 f7 d8 64 89 01 48
RSP: 002b:00007ffdba393f88 EFLAGS: 00000246 ORIG RAX:
000000000000139
RAX: ffffffffffda RBX: 00000000000000 RCX:
00007f64dda564dd
RDX: 000000000000000 RSI: 00005575399e2ab2 RDI:
0000000000000001
RBP: 000055753a91c5e0 R08: 000000000000000 R09:
0000000000000000
R10: 0000000000000001 R11: 000000000000246 R12:
00005575399e2ab2
R13: 000055753a91ceb0 R14: 000000000000000 R15:
000055753a923018
</TASK>
Modules linked in: btintel(+) btmtk bluetooth vfat
snd_hda_codec_hdmi fat snd_hda_codec_realtek
snd_hda_codec_generic iwlmvm(+) snd_sof_pci_intel_tgl
mac80211 snd_sof_intel_hda_common soundwire_intel
soundwire_generic_allocation soundwire_cadence soundwire_bus
snd_sof_intel_hda snd_sof_pci snd_sof snd_sof_xtensa_dsp
snd_soc_hdac_hda snd_hda_ext_core snd_soc_acpi_intel_match
snd_soc_acpi snd_soc_core btrfs snd_compress snd_hda_intel
snd_intel_dspcfg snd_intel_sdw_acpi snd_hda_codec raid6_pq
iwlwifi snd_hda_core snd_pcm snd_timer snd soundcore cfg80211
intel ish ipc(+) thunderbolt rfkill intel ishtp ucsi acpi wmi
```

			ı	ī	T
		i2c_hid_acpi i2c_hid evdev			
		CR2: 00000000000004f [ end trace 00000000000000000000 ]			
		[ cha trace occoodooooo ]			
		Check the debugfs_dir pointer for an error before using it.			
		[change to make both conditional]			
		In the Linux kernel, the following vulnerability has been resolved:			
		the armed, int240; a fix means and lead, in int2400, notify()			
		thermal: int340x: fix memory leak in int3400_notify()			
		It is easy to hit the below memory leaks in my TigerLake platform:			
		it is easy to the are select memory leads in my riger care platform			
		unreferenced object 0xffff927c8b91dbc0 (size 32):			
		comm "kworker/0:2", pid 112, jiffies 4294893323 (age 83.604s)			
		hex dump (first 32 bytes):			
		4e 41 4d 45 3d 49 4e 54 33 34 30 30 20 54 68 65			
		NAME=INT3400 The 72 6d 61 6c 00 6b 6b 6b 6b 6b 6b 6b 6b 6b a5			
		rmal.kkkkkkkkkk.			
		backtrace:			
		[ <ffffff9c502c3e>]kmalloc_track_caller+0x2fe/0x4a0</ffffff9c502c3e>			
		[ <fffffff9c7b7c15>] kvasprintf+0x65/0xd0</fffffff9c7b7c15>			
		[ <fffffff9c7b7d6e>] kasprintf+0x4e/0x70</fffffff9c7b7d6e>			
		[ <fffffffc04cb662>] int3400_notify+0x82/0x120</fffffffc04cb662>			
		[int3400_thermal] [ <ffffffff9c8b7358>] acpi_ev_notify_dispatch+0x54/0x71</ffffffff9c8b7358>			
		[ <fffffff9c88f1a7>] acpi_os_execute_deferred+0x17/0x30</fffffff9c88f1a7>			
		[ <fffffff9c2c2c0a>] process_one_work+0x21a/0x3f0</fffffff9c2c2c0a>			
		[ <fffffff9c2c2e2a>] worker_thread+0x4a/0x3b0</fffffff9c2c2e2a>			
		[ <ffffff9c2cb4dd>] kthread+0xfd/0x130</ffffff9c2cb4dd>			
		[ <fffffff9c201c1f>] ret_from_fork+0x1f/0x30</fffffff9c201c1f>			
CVE-2022-48924	Linux	Fix it by calling kfree() accordingly.	2024-08-22	5.5	Medium
<u>CVL 2022 40324</u>	Liliux	In the Linux kernel, the following vulnerability has been resolved:	2024 00 22	3.3	Wicaram
		<b>6</b> 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
		iio: adc: men_z188_adc: Fix a resource leak in an error handling			
		path			
		If it and a vice the second of			
		If iio_device_register() fails, a previous ioremap() is left unbalanced.			
		unbalanceu.			
		Update the error handling path and add the missing iounmap()			
		call, as			
CVE-2022-48928	Linux	already done in the remove function.	2024-08-22	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		bpf: Fix crash due to out of bounds access into reg2btf_ids.			
		bpr. Fix crash due to out of bounds access into regapti_ids.			
		When commit e6ac2450d6de ("bpf: Support bpf program calling			
		kernel function") added			
		kfunc support, it defined reg2btf_ids as a cheap way to translate			
		the verifier			
		reg type to the appropriate btf_vmlinux BTF ID, however			
		commit c25b2ae13603 ("bpf: Replace PTR_TO_XXX_OR_NULL with PTR_TO_XXX   PTR_MAYBE_NULL")			
		moved theBPF_REG_TYPE_MAX from the last member of			
		bpf_reg_type enum to after			
		the base register types, and defined other variants using type flag			
		composition. However, now, the direct usage of reg->type to index			
		into			
		reg2btf_ids may no longer fall intoBPF_REG_TYPE_MAX range, and hence lead to			
		out of bounds access and kernel crash on dereference of bad			
CVE-2022-48929	Linux	pointer.	2024-08-22	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		DDMA/th and 51 of the Heal			
		RDMA/ib_srp: Fix a deadlock			
		Remove the flush workqueue(system long wq) call since flushing			
		system_long_wq is deadlock-prone and since that call is redundant			
		with a			
CVE-2022-48930	Linux	preceding cancel_work_sync()	2024-08-22	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		not/mlyE. DD. Fix slah aut of have do in make a control of			
		net/mlx5: DR, Fix slab-out-of-bounds in mlx5_cmd_dr_create_fte			
		When adding a rule with 32 destinations, we hit the following out-			
		of-band			
CVE-2022-48932	Linux	access issue:	2024-08-22	5.5	Medium

			1		
		BUG: KASAN: slab-out-of-bounds in mlx5_cmd_dr_create_fte+0x18ee/0x1e70			
		This patch fixes the issue by both increasing the allocated buffers			
		accommodate for the needed actions and by checking the number of actions			
		to prevent this issue when a rule with too many actions is provided.			
		In the Linux kernel, the following vulnerability has been resolved:			
		netfilter: nf_tables: fix memory leak during stateful obj update			
		stateful objects can be updated from the control plane. The transaction logic allocates a temporary object for this purpose.			
		The ->init function was called for this object, so plain kfree() leaks resources. We must call ->destroy function of the object.			
		nft_obj_destroy does this, but it also decrements the module refcount,			
		but the update path doesn't increment it.			
01/5 2022 40022		To avoid special-casing the update object release, do module_get for	2024 00 22		
<u>CVE-2022-48933</u>	Linux	the update case too and release it via nft_obj_destroy().  In the Linux kernel, the following vulnerability has been resolved:	2024-08-22	5.5	Medium
		nfp: flower: Fix a potential leak in nfp_tunnel_add_shared_mac() ida_simple_get() returns an id between min (0) and max			
		(NFP_MAX_MAC_INDEX) inclusive.			
		So NFP_MAX_MAC_INDEX (0xff) is a valid id.			
		In order for the error handling path to work correctly, the 'invalid' value for 'ida_idx' should not be in the 0NFP_MAX_MAC_INDEX			
		range, inclusive.			
CVE-2022-48934	Linux	So set it to -1.	2024-08-22	5.5	Medium
		In the Linux kernel, the following vulnerability has been resolved:			
		netfilter: nf_tables: unregister flowtable hooks on netns exit			
		Unregister flowtable hooks before they are releases via nf_tables_flowtable_destroy() otherwise hook core reports UAF.			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz-			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5-			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz-executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5-syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task></task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:106</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_lvl+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_lvl+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106 print_address_description+0x65/0x380 mm/kasan/report.c:247 mm/kasan/report.c:247</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_lvl+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106 print_address_description+0x65/0x380 mm/kasan/report.c:247 mm/kasan/report.c:247kasan_report mm/kasan/report.c:433 [inline]kasan_report mm/kasan/report.c:433 [inline]</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_lvl+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106 print_address_description+0x65/0x380 mm/kasan/report.c:247kasan_report mm/kasan/report.c:433 [inline]kasan_report mm/kasan/report.c:450 kasan_report+0x19a/0x1f0 mm/kasan/report.c:450</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_IvI+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106 print_address_description+0x65/0x380 mm/kasan/report.c:247kasan_report mm/kasan/report.c:433 [inline]kasan_report mm/kasan/report.c:433 [inline] mm/kasan/report.c:450 kasan_report+0x19a/0x1f0 mm/kasan/report.c:450 mm/kasan/report.c:450 nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_lvl+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106 print_address_description+0x65/0x380 mm/kasan/report.c:247kasan_report mm/kasan/report.c:433 [inline]kasan_report mm/kasan/report.c:430 [inline] mm/kasan/report.c:450 kasan_report+0x19a/0x1f0 mm/kasan/report.c:450 mm/kasan/report.c:450</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_lvl+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106 print_address_description+0x65/0x380 mm/kasan/report.c:247 mm/kasan/report.c:247kasan_report mm/kasan/report.c:433 [inline]kasan_report mm/kasan/report.c:450 kasan_report+0x19a/0x1f0 mm/kasan/report.c:450 mm/kasan/report.c:450 nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142nf_register_net_hook+0x27e/0x8d0 net/netfilter/core.c:429 nf_register_net_hook+0xaa/0x180 net/netfilter/core.c:571</task>			
		nf_tables_flowtable_destroy() otherwise hook core reports UAF.  BUG: KASAN: use-after-free in nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142 Read of size 4 at addr ffff8880736f7438 by task syz- executor579/3666  CPU: 0 PID: 3666 Comm: syz-executor579 Not tainted 5.16.0-rc5- syzkaller #0 Hardware name: Google Google Compute Engine/Google Compute Engine, BIOS Google 01/01/2011 Call Trace: <task>dump_stack lib/dump_stack.c:88 [inline]dump_stack lib/dump_stack.c:88 [inline] lib/dump_stack.c:106 dump_stack_lvl+0x1dc/0x2d8 lib/dump_stack.c:106 lib/dump_stack.c:106 print_address_description+0x65/0x380 mm/kasan/report.c:247kasan_report mm/kasan/report.c:433 [inline]kasan_report mm/kasan/report.c:433 [inline] mm/kasan/report.c:450 kasan_report+0x19a/0x1f0 mm/kasan/report.c:450 mm/kasan/report.c:450 nf_hook_entries_grow+0x5a7/0x700 net/netfilter/core.c:142 net/netfilter/core.c:142nf_register_net_hook+0x27e/0x8d0 net/netfilter/core.c:429 net/netfilter/core.c:429</task>			

		net/netfilter/nf_tables_api.c:7232			
	1	nf_tables_newflowtable+0x2022/0x2cf0			
	I	net/netfilter/nf_tables_api.c:7430			
	1	net/netfilter/nf_tables_api.c:7430			
	1				
	I	nfnetlink_rcv_batch net/netfilter/nfnetlink.c:513 [inline]			
	1	nfnetlink_rcv_skb_batch net/netfilter/nfnetlink.c:634 [inline]			
	1	nfnetlink_rcv_batch net/netfilter/nfnetlink.c:513 [inline]			
	I	net/netfilter/nfnetlink.c:652			
	I	nfnetlink_rcv_skb_batch net/netfilter/nfnetlink.c:634 [inline]			
	I	net/netfilter/nfnetlink.c:652			
	I	nfnetlink_rcv+0x10e6/0x2550 net/netfilter/nfnetlink.c:652			
	I	net/netfilter/nfnetlink.c:652			
	I	het/hetinter/innetinik.c.osz			
	I				
	I	nft_release_hook() calls nft_unregister_flowtable_net_hooks()			
	I	which			
	I	only unregisters the hooks, then after RCU grace period, it is			
	I	guaranteed that no packets add new entries to the flowtable (no			
	I	flow			
	I				
	I	offload rules and flowtable hooks are reachable from packet path),			
	I	so it			
	I	is safe to call nf_flow_table_free() which cleans up the remaining			
	I	entries from the flowtable (both software and hardware) and it			
	l	unbinds			
	1	the flow_block.			
		_			
	I	In the Linux kernel, the following vulnerability has been resolved:			
	l				
	l	CDC-NCM: avoid overflow in sanity checking			
	l				
	1	A broken device may give an extreme offset like 0xFFF0			
	ĺ	and a reasonable length for a fragment. In the sanity			
	l	check as formulated now, this will create an integer			
	I				
	I	overflow, defeating the sanity check. Both offset			
	I	and offset + len need to be checked in such a manner			
	1	that no overflow can occur.			
<u>CVE-2022-48938</u>	Linux	And those quantities should be unsigned.	2024-08-22	5.5	Medium
	1	In the Linux kernel, the following vulnerability has been resolved:			
	1				
	I	bpf: Fix crash due to incorrect copy_map_value			
	I	bpi. Tix drash due to intestreet copy_map_value			
	I	When both had only led and had those on an account in a DDF man			
	1	When both bpf_spin_lock and bpf_timer are present in a BPF map			
		value,			
		value, copy_map_value needs to skirt both objects when copying a value			
		copy_map_value needs to skirt both objects when copying a value			
		copy_map_value needs to skirt both objects when copying a value into and			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g.			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g.			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]#./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel.			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849]			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash   [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel.   [ 16.037849]   =============   [ 16.038458] BUG: KASAN: user-memory-access inpv_queued_spin_lock_slowpath+0x32b/0x520   [ 16.038944] Write of size 8 at addr 0000000000043ec0 by task test_progs/325   [ 16.039399]   [ 16.0399514] CPU: 0 PID: 325 Comm: test_progs Tainted: G OE			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash   [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel.   [ 16.037849]   =============   [ 16.038458] BUG: KASAN: user-memory-access inpv_queued_spin_lock_slowpath+0x32b/0x520   [ 16.038944] Write of size 8 at addr 0000000000043ec0 by task test_progs/325   [ 16.039399]   [ 16.0399514] CPU: 0 PID: 325 Comm: test_progs Tainted: G OE			
		copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash			
CVE-2022-48940	Linux	copy_map_value needs to skirt both objects when copying a value into and out of the map. However, the current code does not set both s_off and t_off in copy_map_value, which leads to a crash when e.g. bpf_spin_lock is placed in map value with bpf_timer, as bpf_map_update_elem call will be able to overwrite the other timer object.  When the issue is not fixed, an overwriting can produce the following splat:  [root@(none) bpf]# ./test_progs -t timer_crash [ 15.930339] bpf_testmod: loading out-of-tree module taints kernel. [ 16.037849] ====================================	2024-08-22	5.5	Medium

		[ 16.043079]bpf_spin_lock_irqsave+0xdf/0xf0			
		[ 16.043366] ? bpf_get_current_comm+0x50/0x50			
		[ 16.043608] ? jhash+0x11a/0x270			
		[ 16.043848] bpf_timer_cancel+0x34/0xe0			
		[ 16.044119] bpf_prog_c4ea1c0f7449940d_sys_enter+0x7c/0x81			
		[ 16.044500] bpf_trampoline_6442477838_0+0x36/0x1000			
		[ 16.044836]x64_sys_nanosleep+0x5/0x140			
		[ 16.045119] do_syscall_64+0x59/0x80			
		[ 16.045377] ? lock_is_held_type+0xe4/0x140			
		[ 16.045670] ? irqentry_exit_to_user_mode+0xa/0x40			
		[ 16.046001] ? mark_held_locks+0x24/0x90			
		[ 16.046287] ? asm_exc_page_fault+0x1e/0x30			
		[ 16.046569] ? asm_exc_page_fault+0x8/0x30			
		[ 16.046851] ? lockdep_hardirqs_on+0x7e/0x100			
		[ 16.047137] entry_SYSCALL_64_after_hwframe+0x44/0xae			
		[ 16.047405] RIP: 0033:0x7f9e4831718d			
		[ 16.047602] Code: b4 0c 00 0f 05 eb a9 66 0f 1f 44 00 00 f3 0f 1e			
		fa 48 89 f8 48 89 f7 48 89 d6 48 89 ca 4d 89 c2 4d 89 c8 4c 8b 4c			
		24 08 0f 05 <48> 3d 01 f0 ff ff 73 01 c3 48 8b 0d b3 6c 0c 00 f7 d8			
		64 89 01 48			
		[ 16.048764] RSP: 002b:00007fff488086b8 EFLAGS: 00000206			
		ORIG_RAX: 000000000000023			
		[ 16.049275] RAX: ffffffffffffda RBX: 00007f9e48683740 RCX:			]
		00007f9e4831718d			]
		[ 16.049747] RDX: 000000000000000 RSI: 0000000000000000			
		RDI: 00007fff488086d0			
		[ 16.050225] RBP: 00007fff488086f0 R08: 00007fff488085d7 R09:			
		00007f9e4cb594a0			]
					[
		[ 16.050648] R10: 000000000000000 R11: 0000000000000			]
		R12: 00007f9e484cde30			
		[ 16.051124] R13: 00000000000000 R14: 000000000000000			]
		R15: 000000000000000			]
		[ 16.051608]			
		[ 16.051762]			
		========			
		In the Linux kernel, the following vulnerability has been resolved:			
		hwmon: Handle failure to register sensor with thermal zone			
		correctly			
		If an attempt is made to a sensor with a thermal zone and it fails,			
		the call to devm_thermal_zone_of_sensor_register() may return -			
		ENODEV.			
		ENODEV.			
		-1.			
		This may result in crashes similar to the following.			
		This may result in crashes similar to the following.			
		This may result in crashes similar to the following.  Unable to handle kernel NULL pointer dereference at virtual			
		Unable to handle kernel NULL pointer dereference at virtual			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd			
		Unable to handle kernel NULL pointer dereference at virtual			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=)			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60 Ir: thermal_zone_device_update+0x40/0x2e0			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60 Ir: thermal_zone_device_update+0x40/0x2e0			
		Unable to handle kernel NULL pointer dereference at virtual address 000000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60 Ir: thermal_zone_device_update+0x40/0x2e0 sp: ffff800014c4fc60			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd Internal error: Oops: 96000021 [#1] PREEMPT SMP pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60 Ir: thermal_zone_device_update+0x40/0x2e0 sp: ffff800014c4fc60 x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60   Ir : thermal_zone_device_update+0x40/0x2e0   sp : ffff800014c4fc60   x29: ffff800014c4fc60   x29: ffff800014c4fc60   x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 000000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790   x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 000000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790   x26: ffff365ee3f6e000 x25: 00000000000000000 x24: ffff365ee3f6e000 x23: ffffdde218426870 x22: ffff365ee3f6e000 x21:			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60   Ir : thermal_zone_device_update+0x40/0x2e0   sp : ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27:   ffffdde218426790   x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 000000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790   x26: ffff365ee3f6e000 x25: 0000000000000000 x24: ffff365ee3f6e000 x23: ffffdde218426870 x22: ffff365ee3f6e000 x21: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60   Ir : thermal_zone_device_update+0x40/0x2e0   sp : ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27:   ffffdde218426790   x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 000000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790   x26: ffff365ee3f6e000 x25: 0000000000000000 x24: ffff365ee3f6e000 x23: ffffdde218426870 x22: ffff365ee3f6e000 x21: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60   Ir : thermal_zone_device_update+0x40/0x2e0   sp : ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790   x26: ffff365ee3f6e000 x25: 0000000000000000 x24: ffff365ee3f6e000 x22: ffffdde218426870 x22: ffff365ee3f6e000 x21: 00000000000003cd   x20: ffff365ee8bf3308 x19: ffffffffffffffed x18: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 0000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790   x26: ffff365ee3f6e000 x25: 0000000000000000 x24: ffff365ee3f6e000 x22: ffff365ee3f6e000 x21: 00000000000003cd   x20: ffff365ee8bf3308 x19: fffffffffffffed x18: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 0000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60 Ir : thermal_zone_device_update+0x40/0x2e0 sp : ffff800014c4fc60 x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790 x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 0000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60  Ir : thermal_zone_device_update+0x40/0x2e0  sp : ffff800014c4fc60  x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffffdde218426790  x26: ffff365ee3f6e000 x25: 0000000000000000 x24: ffff365ee3f6e000 x21: 0000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27:   ffffdde218426790   x26: ffff365ee3f6e000 x25: 000000000000000000 x24:   ffff365ee3f6e000   x23: ffffdde218426870 x22: ffff365ee3f6e000 x21:   00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27:   ffffdde218426790   x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc: mutex_lock+0x18/0x60   Ir: thermal_zone_device_update+0x40/0x2e0   sp: ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27:   ffffdde218426790   x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60 Ir : thermal_zone_device_update+0x40/0x2e0 sp : ffff800014c4fc60 x28: ffff365ee3f6e000 x27: ffff8de218426790 x26: ffff365ee3f6e000 x25: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000003cd  Internal error: Oops: 96000021 [#1] PREEMPT SMP  pstate: 60400009 (nZCv daif +PAN -UAO -TCO -DIT -SSBS BTYPE=) pc : mutex_lock+0x18/0x60   Ir : thermal_zone_device_update+0x40/0x2e0   sp : ffff800014c4fc60   x29: ffff800014c4fc60 x28: ffff365ee3f6e000 x27:   ffffdde218426790   x26: ffff365ee3f6e000 x25: 0000000000000000 x24:   ffff365ee3f6e000   x23: ffffdde218426870 x22: ffff365ee3f6e000 x21:   000000000000003cd   x20: ffff365ee8bf3308 x19: fffffffffffffed x18: 00000000000000   x17: ffffdde21842689c x16: ffffdde1cb7a0b7c x15:   00000000000000000   x14: ffffdde21a4889a0 x13: 000000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
		Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000			
CVE-2022-48942	Linux	Unable to handle kernel NULL pointer dereference at virtual address 00000000000000000000000000000000000	2024-08-22	5.5	Medium

Г				ı	
		irq_thread+0x134/0x240			
		kthread+0x178/0x190 ret from fork+0x10/0x20			
		Code: d503201f d503201f d2800001 aa0103e4 (c8e47c02)			
		Jon Hunter reports that the exact call sequence is:			
		hwmon_notify_event()			
		> hwmon_thermal_notify()			
		> thermal_zone_device_update()			
		> update_temperature()			
		> mutex_lock()			
		The hwmon core needs to handle all errors returned from calls			
		to devm_thermal_zone_of_sensor_register(). If the call fails			
		with -ENODEV, report that the sensor was not attached to a			
		thermal zone but continue to register the hwmon device.			
		Zohocorp ManageEngine Endpoint Central affected by Incorrect			
		authorization vulnerability in remote office deploy			
		configurations. This issue affects Endpoint Central: before			
CVE-2024-38869	ManageEngine	11.3.2416.04 and before 11.3.2400.25.	2024-08-23	5.4	Medium
		Adobe Experience Manager versions 6.5.20 and earlier are			
		affected by a reflected Cross-Site Scripting (XSS) vulnerability. If an			
		attacker is able to convince a victim to visit a URL referencing a vulnerable page, malicious JavaScript content may be executed			
CVE-2024-41841	Adobe	within the context of the victim's browser.	2024-08-23	5.4	Medium
<u> </u>	,	Adobe Experience Manager versions 6.5.20 and earlier are		2.,	caiaiii
		affected by a stored Cross-Site Scripting (XSS) vulnerability that			
		could be abused by an attacker to inject malicious scripts into			
		vulnerable form fields. Malicious JavaScript may be executed in a			
		victim's browser when they browse to the page containing the			
CVE-2024-41843	Adobe	vulnerable field.	2024-08-23	5.4	Medium
		Adobe Experience Manager versions 6.5.20 and earlier are			
		affected by a stored Cross-Site Scripting (XSS) vulnerability that could be abused by an attacker to inject malicious scripts into			
		vulnerable form fields. Malicious JavaScript may be executed in a			
		victim's browser when they browse to the page containing the			
CVE-2024-41844	Adobe	vulnerable field.	2024-08-23	5.4	Medium
		Adobe Experience Manager versions 6.5.20 and earlier are			
		affected by a stored Cross-Site Scripting (XSS) vulnerability that			
		could be abused by an attacker to inject malicious scripts into			
		vulnerable form fields. Malicious JavaScript may be executed in a			
0) /5 2024 44045		victim's browser when they browse to the page containing the	2024 00 22	- 4	
<u>CVE-2024-41845</u>	Adobe	vulnerable field.  Adobe Experience Manager versions 6.5.20 and earlier are	2024-08-23	5.4	Medium
		affected by a stored Cross-Site Scripting (XSS) vulnerability that			
		could be abused by an attacker to inject malicious scripts into			
		vulnerable form fields. Malicious JavaScript may be executed in a			
		victim's browser when they browse to the page containing the			
CVE-2024-41846	Adobe	vulnerable field.	2024-08-23	5.4	Medium
		Adobe Experience Manager versions 6.5.20 and earlier are			
		affected by a reflected Cross-Site Scripting (XSS) vulnerability. If an			
		attacker is able to convince a victim to visit a URL referencing a			
CVE-2024-41847	Adobe	vulnerable page, malicious JavaScript content may be executed within the context of the victim's browser.	2024-08-23	5.4	Medium
CVL-2024-4104/	Auone	Adobe Experience Manager versions 6.5.20 and earlier are	∠∪∠ <del>1</del> -∪0-23	J.4	ivicululli
		affected by a reflected Cross-Site Scripting (XSS) vulnerability. If an			
		attacker is able to convince a victim to visit a URL referencing a			
		vulnerable page, malicious JavaScript content may be executed			
CVE-2024-41848	Adobe	within the context of the victim's browser.	2024-08-23	5.4	Medium
T		Adobe Experience Manager versions 6.5.20 and earlier are			
		affected by a stored Cross-Site Scripting (XSS) vulnerability that			
		could be abused by an attacker to inject malicious scripts into			
		vulnerable form fields. Malicious JavaScript may be executed in a victim's browser when they browse to the page containing the			
CVE-2024-41875	Adobe	vulnerable field.	2024-08-23	5.4	Medium
2.2.232.1120/3		Adobe Experience Manager versions 6.5.20 and earlier are		3.1	
		affected by a reflected Cross-Site Scripting (XSS) vulnerability. If an			
		attacker is able to convince a victim to visit a URL referencing a			
		vulnerable page, malicious JavaScript content may be executed			
CVE-2024-41876	Adobe	within the context of the victim's browser.	2024-08-23	5.4	Medium
		Adobe Experience Manager versions 6.5.19 and earlier are			
		affected by a stored Cross-Site Scripting (XSS) vulnerability that			
		could be abused by an attacker to inject malicious scripts into			
		vulnerable form fields. Malicious JavaScript may be executed in a victim's browser when they browse to the page containing the			
CVE-2024-41877	Adobe	vulnerable field.	2024-08-23	5.4	Medium
<u> </u>	Adobe	Adobe Experience Manager versions 6.5.19 and earlier are	2027 00 23	J. <del>T</del>	Medialii
		The same of the sa		1	i
CVE-2024-41878	Adobe	affected by a DOM-based Cross-Site Scripting (XSS) vulnerability.	2024-08-23	5.4	Medium

1		I			T
		This vulnerability could allow an attacker to inject and execute			
		arbitrary JavaScript code within the context of the user's browser session. Exploitation of this issue requires user interaction, such as			
		convincing a victim to click on a malicious link.			
		A vulnerability was found in D-Link DNS-120, DNR-202L, DNS-315L,			
		DNS-320, DNS-320L, DNS-320LW, DNS-321, DNR-322L, DNS-323,			
		DNS-325, DNS-326, DNS-327L, DNR-326, DNS-340L, DNS-343, DNS-			
		345, DNS-726-4, DNS-1100-4, DNS-1200-05 and DNS-1550-04 up			
		to 20240814 and classified as critical. Affected by this issue is the			
		function			
		cgi_audio_search/cgi_create_playlist/cgi_get_album_all_tracks/cg			
		i_get_alltracks_editlist/cgi_get_artist_all_album/cgi_get_genre_all			
		_tracks/cgi_get_tracks_list/cgi_set_airplay_content/cgi_write_pla			
		ylist of the file /cgi-bin/myMusic.cgi. The manipulation leads to			
		command injection. The attack may be launched remotely. The exploit has been disclosed to the public and may be used. NOTE:			
		This vulnerability only affects products that are no longer			
		supported by the maintainer. NOTE: Vendor was contacted early			
		and confirmed that the product is end-of-life. It should be retired			
CVE-2024-7922	D-Link	and replaced.	2024-08-19	5.3	Medium
		A vulnerability classified as critical was found in D-Link DNS-120,			
		DNR-202L, DNS-315L, DNS-320, DNS-320L, DNS-320LW, DNS-321,			
		DNR-322L, DNS-323, DNS-325, DNS-326, DNS-327L, DNR-326, DNS-			
		340L, DNS-343, DNS-345, DNS-726-4, DNS-1100-4, DNS-1200-05			
		and DNS-1550-04 up to 20240814. This vulnerability affects the			
		function cgi_unzip of the file /cgi-bin/webfile_mgr.cgi of the			
		component HTTP POST Request Handler. The manipulation of the			
		argument path leads to command injection. The attack can be			
		initiated remotely. The exploit has been disclosed to the public and may be used. NOTE: This vulnerability only affects products			
		that are no longer supported by the maintainer. NOTE: Vendor			
		was contacted early and confirmed that the product is end-of-life.			
CVE-2024-8127	D-Link	It should be retired and replaced.	2024-08-24	5.3	Medium
		A vulnerability, which was classified as critical, has been found in			
		D-Link DNS-120, DNR-202L, DNS-315L, DNS-320, DNS-320L, DNS-			
		320LW, DNS-321, DNR-322L, DNS-323, DNS-325, DNS-326, DNS-			
		327L, DNR-326, DNS-340L, DNS-343, DNS-345, DNS-726-4, DNS-			
		1100-4, DNS-1200-05 and DNS-1550-04 up to 20240814. This issue affects the function cgi add zip of the file /cgi-			
		bin/webfile mgr.cgi of the component HTTP POST Request			
		Handler. The manipulation of the argument path leads to			
		command injection. The attack may be initiated remotely. The			
		exploit has been disclosed to the public and may be used. NOTE:			
		This vulnerability only affects products that are no longer			
		supported by the maintainer. NOTE: Vendor was contacted early			
		and confirmed that the product is end-of-life. It should be retired			
CVE-2024-8128	D-Link	and replaced.	2024-08-24	5.3	Medium
		A vulnerability, which was classified as critical, was found in D-Link			
		DNS-120, DNR-202L, DNS-315L, DNS-320, DNS-320L, DNS-320LW, DNS-321, DNR-322L, DNS-323, DNS-325, DNS-326, DNS-327L, DNR-			
		326, DNS-340L, DNS-343, DNS-345, DNS-726-4, DNS-1100-4, DNS-			
		1200-05 and DNS-1550-04 up to 20240814. Affected is the			
		function cgi_s3_modify of the file /cgi-bin/s3.cgi of the component			
		HTTP POST Request Handler. The manipulation of the argument			
		f_job_name leads to command injection. It is possible to launch			
		the attack remotely. The exploit has been disclosed to the public			
		and may be used. NOTE: This vulnerability only affects products			
		that are no longer supported by the maintainer. NOTE: Vendor			
CVF 2024 8120	Dink	was contacted early and confirmed that the product is end-of-life.	2024 00 24	гэ	Madium
CVE-2024-8129	D-Link	It should be retired and replaced.  A vulnerability has been found in D-Link DNS-120, DNR-202L, DNS-	2024-08-24	5.3	Medium
		315L, DNS-320, DNS-320L, DNS-320LW, DNS-321, DNR-322L, DNS-			
		323, DNS-325, DNS-326, DNS-327L, DNR-326, DNS-340L, DNS-343,			
		DNS-345, DNS-726-4, DNS-1100-4, DNS-1200-05 and DNS-1550-04			
		up to 20240814 and classified as critical. Affected by this			
		vulnerability is the function cgi_s3 of the file /cgi-bin/s3.cgi of the			
		component HTTP POST Request Handler. The manipulation of the			
		argument f_a_key leads to command injection. The attack can be			
		launched remotely. The exploit has been disclosed to the public			
		and may be used. NOTE: This vulnerability only affects products			
		that are no longer supported by the maintainer. NOTE: Vendor was contacted early and confirmed that the product is end-of-life.			
CVE-2024-8130	D-Link	It should be retired and replaced.	2024-08-24	5.3	Medium
<u> </u>	- LIIIN	A vulnerability was found in D-Link DNS-120, DNR-202L, DNS-315L,	_5215527	3.5	caraiii
		DNS-320, DNS-320L, DNS-320LW, DNS-321, DNR-322L, DNS-323,			
		DNS-325, DNS-326, DNS-327L, DNR-326, DNS-340L, DNS-343, DNS-			
		345, DNS-726-4, DNS-1100-4, DNS-1200-05 and DNS-1550-04 up			
		to 20240814 and classified as critical. Affected by this issue is the			
01/5 000 1 5 15		function module_enable_disable of the file /cgi-bin/apkg_mgr.cgi	200 - 5		
CVE-2024-8131	D-Link	of the component HTTP POST Request Handler. The manipulation	2024-08-24	5.3	Medium

		of the argument f_module_name leads to command injection. The attack may be launched remotely. The exploit has been disclosed to the public and may be used. NOTE: This vulnerability only affects products that are no longer supported by the maintainer. NOTE: Vendor was contacted early and confirmed that the product is end-of-life. It should be retired and replaced.  A vulnerability was found in D-Link DNS-120, DNR-202L, DNS-315L, DNS-320, DNS-320L, DNS-320LW, DNS-321, DNR-322L, DNS-323, DNS-325, DNS-326, DNS-327L, DNR-326, DNS-340L, DNS-343, DNS-			
		345, DNS-726-4, DNS-1100-4, DNS-1200-05 and DNS-1550-04 up to 20240814. It has been classified as critical. This affects the function webdav_mgr of the file /cgi-bin/webdav_mgr.cgi of the component HTTP POST Request Handler. The manipulation of the			
		argument f_path leads to command injection. It is possible to initiate the attack remotely. The exploit has been disclosed to the public and may be used. NOTE: This vulnerability only affects products that are no longer supported by the maintainer. NOTE:			
CVE-2024-8132	D-Link	Vendor was contacted early and confirmed that the product is end-of-life. It should be retired and replaced.	2024-08-24	5.3	Medium
		A vulnerability was found in D-Link DNS-120, DNR-202L, DNS-315L, DNS-320, DNS-320L, DNS-320LW, DNS-321, DNR-322L, DNS-323, DNS-325, DNS-326, DNS-327L, DNR-326, DNS-340L, DNS-343, DNS-345, DNS-726-4, DNS-1100-4, DNS-1200-05 and DNS-1550-04 up			
		to 20240814. It has been declared as critical. This vulnerability affects the function cgi_FMT_R5_SpareDsk_DiskMGR of the file /cgi-bin/hd_config.cgi of the component HTTP POST Request			
		Handler. The manipulation of the argument f_source_dev leads to command injection. The attack can be initiated remotely. The exploit has been disclosed to the public and may be used. NOTE: This vulnerability only affects products that are no longer			
		supported by the maintainer. NOTE: Vendor was contacted early and confirmed that the product is end-of-life. It should be retired			
CVE-2024-8133	D-Link	and replaced.	2024-08-24	5.3	Medium
		A vulnerability was found in D-Link DNS-120, DNR-202L, DNS-315L, DNS-320, DNS-320L, DNS-320LW, DNS-321, DNR-322L, DNS-323, DNS-325, DNS-326, DNS-327L, DNR-326, DNS-340L, DNS-343, DNS-345, DNS-726-4, DNS-1100-4, DNS-1200-05 and DNS-1550-04 up			
		to 20240814. It has been rated as critical. This issue affects the			
		function cgi_FMT_Std2R5_1st_DiskMGR of the file /cgi-bin/hd_config.cgi of the component HTTP POST Request Handler.			
		The manipulation of the argument f_source_dev leads to command injection. The attack may be initiated remotely. The			
		exploit has been disclosed to the public and may be used. NOTE: This vulnerability only affects products that are no longer			
		supported by the maintainer. NOTE: Vendor was contacted early and confirmed that the product is end-of-life. It should be retired			
CVE-2024-8134	D-Link	and replaced.  Adobe Experience Manager versions 6.5.20 and earlier are	2024-08-24	5.3	Medium
		affected by a stored Cross-Site Scripting (XSS) vulnerability that could be abused by an attacker to inject malicious scripts into vulnerable form fields. Malicious JavaScript may be executed in a			
CVE-2024-41842	Adobe	victim's browser when they browse to the page containing the vulnerable field.  In the Linux kernel, the following vulnerability has been resolved:	2024-08-23	4.8	Medium
		configfs: fix a race in configfs_{,un}register_subsystem()			
		When configfs_register_subsystem() or configfs_unregister_subsystem() is executing link_group() or unlink_group(),			
		it is possible that two processes add or delete list concurrently.  Some unfortunate interleavings of them can cause kernel panic.			
		One of cases is: A> B> C> D A < B < C < D			
		delete list_head *B   delete list_head *C			
		configfs_unregister_subsystem   configfs_unregister_subsystem unlink_group   unlink_group   unlink_obj   list_dol_init			
		list_del_init   list_del_initlist_del_entry  list_del_entrylist_del  list_del // next == C			
		next->prev = prev			
CVE-2022-48931	Linux	prev->next = next   	2024-08-22	4.7	Medium

Т					1
		prev->next = next			
		Fix this by adding mutex when calling link_group() or			
		unlink_group(), but parent configfs_subsystem is NULL when config_item is root.			
		So I create a mutex configfs_subsystem_mutex.			
		In the Linux kernel, the following vulnerability has been resolved:			
		ice: fix concurrent reset and removal of VFs			
		Commit c503e63200c6 ("ice: Stop processing VF messages during			
		teardown") introduced a driver state flag, ICE_VF_DEINIT_IN_PROGRESS,			
		which is intended to prevent some issues with concurrently handling			
		messages from			
		VFs while tearing down the VFs.			
		This change was motivated by crashes caused while tearing down			
		and bringing up VFs in rapid succession.			
		It turns out that the fix actually introduces issues with the VF			
		driver caused because the PF no longer responds to any messages sent			
		by the VF during its .remove routine. This results in the VF potentially			
		removing			
		its DMA memory before the PF has shut down the device queues.			
		Additionally, the fix doesn't actually resolve concurrency issues within			
		the ice driver. It is possible for a VF to initiate a reset just prior			
		to the ice driver removing VFs. This can result in the remove task concurrently operating while the VF is being reset. This results in			
		similar memory corruption and panics purportedly fixed by that commit.			
		Fix this concurrency at its root by protecting both the reset and			
		removal flows using the existing VF cfg_lock. This ensures that we cannot remove the VF while any outstanding critical tasks such as			
		a virtchnl message or a reset are occurring.			
		This locking change also fixes the root cause originally fixed by			
		commit c503e63200c6 ("ice: Stop processing VF messages during			
		teardown"), so we			
		can simply revert it.			
		Note that I kept these two changes together because simply reverting the			
		original commit alone would leave the driver vulnerable to worse			
CVE-2022-48941	Linux	race conditions.	2024-08-22	4.7	Medium
		Access control for plugin data sources protected by the ReqActions			
		json field of the plugin.json is bypassed if the user or service account is granted associated access to any other data source, as			
		the ReqActions check was not scoped to each specific datasource.  The account must have prior query access to the impacted			
CVE-2024-6322	Grafana	datasource.	2024-08-20	4.4	Medium
		Inappropriate implementation in Permissions in Google Chrome prior to 128.0.6613.84 allowed a remote attacker to perform UI			
CVE-2024-7975	Google	spoofing via a crafted HTML page. (Chromium security severity: Medium)	2024-08-21	4.3	Medium
CVL-2024-73/3	Google	Inappropriate implementation in FedCM in Google Chrome prior	2024-00-21	4.3	ivieululli
		to 128.0.6613.84 allowed a remote attacker to perform UI spoofing via a crafted HTML page. (Chromium security severity:			
CVE-2024-7976	Google	Medium)	2024-08-21	4.3	Medium
		Insufficient policy enforcement in Data Transfer in Google Chrome prior to 128.0.6613.84 allowed a remote attacker who convinced a			
CVE-2024-7978	Google	user to engage in specific UI gestures to leak cross-origin data via a crafted HTML page. (Chromium security severity: Medium)	2024-08-21	4.3	Medium
CVL-2U24-/3/8	Google	Inappropriate implementation in Views in Google Chrome prior to	2024-00-21	4.3	ivieululii
CVE-2024-7981	Google	128.0.6613.84 allowed a remote attacker to perform UI spoofing via a crafted HTML page. (Chromium security severity: Low)	2024-08-21	4.3	Medium
<u> </u>		Inappropriate implementation in WebApp Installs in Google			caram
CVE-2024-8033	Google	Chrome on Windows prior to 128.0.6613.84 allowed an attacker who convinced a user to install a malicious application to perform	2024-08-21	4.3	Medium
	<del>_</del>			·	

		UI spoofing via a crafted HTML page. (Chromium security severity:			
		Low) Inappropriate implementation in Custom Tabs in Google Chrome			
		on Android prior to 128.0.6613.84 allowed a remote attacker to			
CVE 2024 8024	Canala	perform UI spoofing via a crafted HTML page. (Chromium security	2024 00 24	4.2	NA o alicens
CVE-2024-8034	Google	severity: Low) Inappropriate implementation in Extensions in Google Chrome on	2024-08-21	4.3	Medium
		Windows prior to 128.0.6613.84 allowed a remote attacker to			
		perform UI spoofing via a crafted HTML page. (Chromium security			
CVE-2024-8035	Google	severity: Low)	2024-08-21	4.3	Medium
		IBM Sterling Connect:Direct Web Services 6.0, 6.1, 6.2, and 6.3 is			
		vulnerable to cross-site request forgery which could allow an attacker to execute malicious and unauthorized actions			
CVE-2024-39744	IBM	transmitted from a user that the website trusts.	2024-08-22	4.3	Medium
		Adobe Experience Manager versions 6.5.20 and earlier are			
		affected by an Improper Input Validation vulnerability that could			
		lead to a security feature bypass. An low-privileged attacker could			
		leverage this vulnerability to slightly affect the integrity of the page. Exploitation of this issue requires user interaction and scope			
CVE-2024-41849	Adobe	is changed.	2024-08-23	4.1	Medium
CVL 2024 41043	Adobe	In the Linux kernel, the following vulnerability has been resolved:	2024 00 23	7.1	iviculani
		,			
		io_uring: add a schedule point in io_add_buffers()			
		Looping ~65525 times doing kmalled/) calls can trigger soft			
		Looping ~65535 times doing kmalloc() calls can trigger soft lockups,			
		especially with DEBUG features (like KASAN).			
		. , ,			
		[ 253.536212] watchdog: BUG: soft lockup - CPU#64 stuck for 26s!			
		[b219417889:12575]			
		[ 253.544433] Modules linked in: vfat fat i2c_mux_pca954x i2c_mux spidev cdc_acm xhci_pci xhci_hcd sha3_generic gq(O)			
		[ 253.544451] CPU: 64 PID: 12575 Comm: b219417889 Tainted: G			
		S O 5.17.0-smp-DEV #801			
		[ 253.544457] RIP: 0010:kernel_text_address (./include/asm-			
		generic/sections.h:192 ./include/linux/kallsyms.h:29			
		kernel/extable.c:67 kernel/extable.c:98)			
		[ 253.544464] Code: 0f 93 c0 48 c7 c1 e0 63 d7 a4 48 39 cb 0f 92 c1 20 c1 0f b6 c1 5b 5d c3 90 0f 1f 44 00 00 55 48 89 e5 41 57 41			
		56 53 48 89 fb <48> c7 c0 00 00 80 a0 41 be 01 00 00 00 48 39 c7			
		72 Oc 48 c7 c0 40			
		[ 253.544468] RSP: 0018:ffff8882d8baf4c0 EFLAGS: 00000246			
		[ 253.544471] RAX: 1ffff1105b175e00 RBX: ffffffffa13ef09a RCX:			
		00000000a13ef001			
		[ 253.544474] RDX: ffffffffa13ef09a RSI: ffff8882d8baf558 RDI: ffffffffa13ef09a			
		[ 253.544476] RBP: ffff8882d8baf4d8 R08: ffff8882d8baf5e0 R09:			
		000000000000004			
		[ 253.544479] R10: ffff8882d8baf5e8 R11: ffffffffa0d59a50 R12:			
		ffff8882eab20380			
		[ 253.544481] R13: ffffffffa0d59a50 R14: dffffc0000000000 R15: 1ffff1105b175eb0			
		[ 253.544483] FS: 00000000016d3380(0000)			
		GS:ffff88af48c00000(0000) knlGS:000000000000000			
		[ 253.544486] CS: 0010 DS: 0000 ES: 0000 CR0:			
		000000080050033			
		[ 253.544488] CR2: 00000000004af0f0 CR3: 00000002eabfa004			
		CR4: 0000000003706e0 [ 253.544491] DR0: 00000000000000 DR1: 000000000000000000000000000000000000			
		DR2: 000000000000000000000000000000000000			
		[ 253.544492] DR3: 00000000000000 DR6: 00000000fffe0ff0			
		DR7: 000000000000400			
		[ 253.544494] Call Trace:			
		[ 253.544496] <task></task>			
		[ 253.544498]? io_queue_sqe (fs/io_uring.c:7143) [ 253.544505]kernel_text_address (kernel/extable.c:78)			
		[ 253.544508] unwind_get_return_address			
		(arch/x86/kernel/unwind_frame.c:19)			
		[ 253.544514] arch_stack_walk (arch/x86/kernel/stacktrace.c:27)			
		[ 253.544517] ? io_queue_sqe (fs/io_uring.c:7143)			
		[ 253.544521] stack_trace_save (kernel/stacktrace.c:123) [ 253.544527] kasan kmalloc (mm/kasan/common.c:39			
		mm/kasan/common.c:45 mm/kasan/common.c:436			
		mm/kasan/common.c:515)			
		[ 253.544531] ?kasan_kmalloc (mm/kasan/common.c:39			
		mm/kasan/common.c:45 mm/kasan/common.c:436			
		mm/kasan/common.c:515)			
		[ 253.544533] ?kasan_kmalloc (mm/kasan/common.c:524)			
CVE-2022-48937	Linux	[ 253.544535] ? kmem_cache_alloc_trace (./include/linux/kasan.h:270 mm/slab.c:3567)	2024-08-22	3.3	Low
CVL-2022-4033/	LIIIUX	(./ include/ intus/ kasan.ii.2/0 ililii/ slab.C.550/)	2024-00-22	ا ع.ت	LUW

			ı		
		[ 253.544541] ? io_issue_sqe (fs/io_uring.c:4556			
		fs/io_uring.c:4589 fs/io_uring.c:6828)			
		[ 253.544544] ?io_queue_sqe (fs/io_uring.c:?)			
		[ 253.544551]kasan_kmalloc (mm/kasan/common.c:524)			
		[ 253.544553] kmem_cache_alloc_trace			
		(./include/linux/kasan.h:270 mm/slab.c:3567)			
		[ 253.544556] ? io_issue_sqe (fs/io_uring.c:4556			
		fs/io_uring.c:4589 fs/io_uring.c:6828)			
		[ 253.544560] io issue sqe (fs/io uring.c:4556 fs/io uring.c:4589			
		fs/io_uring.c:6828)			
		[ 253.544564] ?kasan_slab_alloc (mm/kasan/common.c:45			
		mm/kasan/common.c:436 mm/kasan/common.c:469)			
		[ 253.544567] ?kasan_slab_alloc (mm/kasan/common.c:39			
		mm/kasan/common.c:45 mm/kasan/common.c:436			
		mm/kasan/common.c:469)			
		[ 253.544569] ? kmem_cache_alloc_bulk (mm/slab.h:732			
		mm/slab.c:3546)			
		[ 253.544573]?io_alloc_req_refill (fs/io_uring.c:2078)			
		[ 253.544578] ? io_submit_sqes (fs/io_uring.c:7441)			
		[ 253.544581] ?se_sys_io_uring_enter (fs/io_uring.c:10154			
		fs/io_uring.c:10096)			
		[ 253.544584] ?x64_sys_io_uring_enter (fs/io_uring.c:10096)			
		[ 253.544587] ? do_syscall_64 (arch/x86/entry/common.c:50			
		arch/x86/entry/common.c:80)			
		[ 253.544590] ? entry_SYSCALL_64_after_hwframe (??:?)			
		[ 253.544596]io_queue_sqe (fs/io_uring.c:?)			
		[ 253.544600] io_queue_sqe (fs/io_uring.c:7143)			
		[ 253.544603] io_submit_sqe (fs/io_uring.c:?)			
		[ 253.544608] io_submit_sqes (fs/io_uring.c:?)			
		[ 253.544612]se_sys_io_uring_enter (fs/io_uring.c:10154			
		fs/io_uri			
		truncated			
		In the Linux kernel, the following vulnerability has been resolved:			
		bpf: Add schedule points in batch ops			
		ap as someware points in saton ops			
		syzbot reported various soft lockups caused by bpf batch			
		operations.			
		INITO the state to the state of factors and the state of			
		INFO: task kworker/1:1:27 blocked for more than 140 seconds.			
		INFO: task hung in rcu_barrier			
		Nothing prevents batch ops to process huge amount of data,			
		we need to add schedule points in them.			
		Note that maybe_wait_bpf_programs(map) calls from			
		generic_map_delete_batch() can be factorized by moving			
		the call after the loop.			
		·			
		This will be done later in -next tree once we get this fix merged,			
CVE-2022-48939	Linux	unless there is strong opinion doing this optimization sooner.	2024-08-22	3.3	Low
	1	O - F			

Where NCA provides the vulnerability information as published by NIST's وحيث تقدم الهيئة تفاصيل الثغرات كما تم نشرها من قبل NIST's NVD. In addition, it is the entity's or individual's responsibility to ensure the implementation of appropriate recommendations.